

Internal ID	Date	Document Number	Item	Quantity	RLC Asset / Street	Request Details
2097217	18/03/2022	14594	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Michael Place Drainage Reserve PK000301	Minor boundary reduction on Oak behind 15a Michael place, remove epis. 3hrs (after speaking with the customer there may be some cherry trees also need to be reduced off their property?)
2097217	18/03/2022	14594	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	4	Michael Place Drainage Reserve PK000301	Minor boundary reduction on Oak behind 15a Michael place, remove epis. 3hrs (after speaking with the customer there may be some cherry trees also need to be reduced off their property?)
2258008	23/06/2022	15845	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Centennial Park PK000303	Tree Trust, Centennial Park Remove Maytanus tree down to ground level, leave stump as low as possible, remove all material from site. Please program for after July 1st 2021. - Block 2 Sect I Site 6 - Block 2 Sect J Site 6
2176679	9/05/2022	15204	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Holdens Ave PK000698	5 Holden AVenue (7 Holden Ave) Program this Pin Oak for removal in July/Aug 21 - Michael Barton. Poles 225970 - 760877. 760877 leads to another pole by the house however there is no pole number - enquire with Unison about this. Please call Mike 021777511 when scheduling this work in.
2112845	29/03/2022	14715	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Shirley Street Esplanade Reserve PK000310	Weed trees behind no.5 on the stream bank to remove. Access through the property - leave firewood ringed up for customer. - Remove 4 Wattles (1 lge, 3 sml) - Remove 1 cherry (med) - Prune side of plum tree that is over the stream - leave property side (they eat them) If we need access to the back gate to give cust a call to open it, her number: (021) 1503084
1978965	17/01/2022	13700	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	TiTokorangi Forest Park PK000260	Tarawera Rd near the intersection with Highfield Drive. Remove large dead wattle. Please ring up all for firewood as we don't want any chainsaws in the hands of the public in the reserve. See attached for location. Please let Kathryn here in the office know when you are scheduling this in as she would appreciate the wood. Thanks
2364185	31/08/2022	16632	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Waikuta Road PK001089	Outside 36, 38, 40 Gleditsia's and Albizia need line clearance, deadwood and general maintenance 237606 - 237602 Along with all tree maintenance in collector for this street

Work Description	REQ / RFS	Case Number	Field Service Actions Taken
	558465 608926	46431	Began boundary reduction of Prunus Serrulata and quercus robur from property as well as removing failed ivy covered prunus and salix which were leaning on the fence. Half a day left to finish boundary reduction and another half a day should we remove a few more ivy ridden prunus/salix which as in poor form and condition.
	558465 608926	46431	Began boundary reduction of Prunus Serrulata and quercus robur from property as well as removing failed ivy covered prunus and salix which were leaning on the fence. Half a day left to finish boundary reduction and another half a day should we remove a few more ivy ridden prunus/salix which as in poor form and condition.
	561641	46772	Done as requested. Completed.
	403142 609510	49119	Removed one large tree. Power box by stump to be partly done.
	572112	49451	Removed medium cherry tree.
		49676	Dismantled dead wattle tree. 500mm -1000mm dbh Wood cut into rings Job complete
	578896	51304	Lift canopies throughout street completed

1991485	21/01/2022	13785	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Haupapa Street PK000672	1181 Haupapa St, CDB. Outside the Central Health Medical Centre Please remove large old Liquidambar due to excessive decay in the trunk and the tree being in a highly pedestrian area. Please remove before December 2021 before the summer stormy season. The decision to remove the tree is in relation to the VTA Report done by Jon Higgs. Report is in the Shared folder - Trees - Tree Assessments and Reports - VTA Reports.
2111079	28/03/2022	14698	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Joanne Crescent Drainage Reserve PK000300	Remove willows only to allow light corridor into property (7a Beryl Pl) and several privet, poison stumps, cut and leave debris down onsite with water way clear. Approx 5 hours. Access from Jade pl photos attached
2111079	28/03/2022	14698	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	5	Joanne Crescent Drainage Reserve PK000300	Remove willows only to allow light corridor into property (7a Beryl Pl) and several privet, poison stumps, cut and leave debris down onsite with water way clear. Approx 5 hours. Access from Jade pl photos attached
2111079	28/03/2022	14698	Tree Removal - <5m Ht	10	Joanne Crescent Drainage Reserve PK000300	Remove willows only to allow light corridor into property (7a Beryl Pl) and several privet, poison stumps, cut and leave debris down onsite with water way clear. Approx 5 hours. Access from Jade pl photos attached
2032502	16/02/2022	14085	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Pegasus Drive PK000383	Elm tree outside 334 Pukehangi St on Pegasus Drive side of the property. Remove Elm tree. Cut roots in the berm that are growing under the driveway to facilitate driveway repairs. Can you let me know the date so i can communicate the timing of the removal with interested parties.
2022424	8/02/2022	14007	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Linton Park East Reserve PK000030	Meet with Mars Remove 1 double leader poplar and crown lift 1 willow. entrance opp. 68 Sunset Road
2210779	31/05/2022	15468	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Kauae Cemetery Reserve PK000748	Remove dead tree. See attached
2396570	14/09/2022	16918	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Arawa Street PK000512	1286 ARAWA ST - Could you please schedule the removal of this declining Kowhai outside 1286 Arawa St, please have the removal completed by Feb 2022. The structure is deteriorating and the growth is getting leggy, there are no good internal reduction points to bring it back to. Paul can you please plant another Kowhai there next winter? ONCE DONE PLSE ADVISE PAUL TO PLANT ANOTHER KOWHAI THERE NEXT WINTER
1968679	10/01/2022	13601	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	General Scheduled Rates - Activities	TWO LARGE TREES HAVE COME DOWN IN THE CHAPMAN PLACE RESERVE. ONE WILLOW AND ONE LEMONWOOD. THEY ARE DIRECTLY BEHIND 38 CHAPMAN

586945	53160	Left spars standing from tree, removed branches chipped left site tidy. Job incomplete, aprox half day with hiab lifter, to remove rest of tree.
585110 608978	53296	Removed willow tree and small privets to allow more light into property.job complete
585110 608978	53296	Removed willow tree and small privets to allow more light into property.job complete
585110 608978	53296	Removed willow tree and small privets to allow more light into property.job complete
589212	53808	Removed variegated elm tree for driveway repairs. Root pruning/stumpgrinding yet be to done.
591852	54531	Removed co dominant Populus and began end weight reduction on large Salix babylonia One day left for reduction on Salix
WD-60899	55367	Remove dead tree completed
EMAILED	56046	Remove tree completed stump to grind
598017	56410	Removed 1 willow tree. Job not complete

2681337	10/03/2023	19076	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Fenton Street PK000345	286 FENTON STREET Cordyline in serious decline. Looks unsightly. Removal necessary. Emerald lodge manager has requested there to be no replacement after the removal of this tree. 2 persons to complete will take approx 1 hour
1972917	12/01/2022	13647	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	6		Remove 6 Melia's prior to shared path being installed. See attached
1971031	11/01/2022	13625	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	General Scheduled Rates - Activities	Tree fallen over pathway Enter reserve between 77 & 79 Wrigley road turn right and it's directly behind #75 Wrigley Rd
1972085	12/01/2022	13638	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Pererika Street PK000386	Michael.Barton@rotorualc.nz Hi There Please remove the Prunus cerasifera in front of 76 Pererika st to enable the construction of a driveway. Please remove before Wednesday next week - Jan 19th.
2843502	9/06/2023	20193	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Flemington Place PK000349	
2537682	6/12/2022	17983	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	14	Homedale Street Reserve PK000004	Privet needs to be removed and chipped behind 17 Homedale. 1 day full crew. Access from Edmond Road into reserve. Only chip if possible. Dry days only
2145278	19/04/2022	14969	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Hamurana Reserve PK000484	1/ Undertake a full crown reduction by 25% to the large English Oak tree growing by the roadside approximately 200m east of the playground and public toilets. This tree is the middle tree of 3 Oaks in this area between the road and a row of conifers. Pic of tree location attached 2/ OPP 645 HAMURANA ROAD - Large liquidambar snap out Medium cherry broken Small pitto broken Reactive prune liquidambar Removed cherry and pitto 3/ There are issues that need to be addressed as a priority first then other maintenance works discussed can be attended to after that, the issues to be focussed on first are: • Snapped, half dead and fully dead trees removed • All stumps (old and new) all over the reserve ground out and reinstated to allow for better grass mowing • English Oak weight reduction opposite golf course • Crown lifting over the shared path through the whole reserve • Bamboo cleared from the powerlines opposite 561 Hamurana Road to facilitate full removal of it at ground level by machine • Powerline applications submitted to Unison to get the rest of the Powerline work that was not done last year
2000346	26/01/2022	13847	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Tutanekai Street PK001071	1199 Tutanekai St Hi lan Please remove dead Plagianthus in garden bed by the crossing. (outside Simply Different)

598185	57079	Removed dead standing Cordolyne australis from roadside Berm Stump to be ground
Emailed	57087	
600479	57418	Tree fallen next to stream and on fence. Tree removed job complete
600191	57422	Removed prunus tree. 7.2 removal Job complete
665748	57552	
596814	58072	Remove tree's as required completed

IFx000010 59161 58073

602259	58076	Removed dead plagianthus in group outside simply different store Job complete
--------	-------	--

2189788	17/05/2022	15314	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Ngongotaha Road PK000890	125A NGONGOTAHA ROAD - THE TREE OUTSIDE Deadwood and crownlift Collector updated. Also, crepe myrtle that has snapped off at the base and been pushed to the side. Can you please chip this up at the same time. See attached
2015083	2/02/2022	13943	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Aquarius Drive Stream Reserve PK000092	Clear branch for mowers
2171891	5/05/2022	15163	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park East Reserve PK000030	2 x pussy willow to remove from bridge and walkway. Debris to be chipped. Best access from Edmund road. 4 hours full crew
2052167	24/02/2022	14257	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Okere Road Recreation Reserve PK000074	Entranceway is overgrown. See attached pics. Ian & Tux to schedule works for Arbs team to attend
2041456	21/02/2022	14162	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Te Akau Rd Reserve PK000174	Remove very dead willow in attached photo and deadwood / weight reduction on one next to it. Remove Liquidambar see attached, it lost a limb over the weekend and is in very poor structural health. see collector
2020875	9/02/2022	13990	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Kuirau Park PK000025	SMALL OAK TREE HAS FALLEN OVER KUIRAU PARK SIDE OF THE AQUATIC CENTRE, NEAR THE PATH THAT GOES THROUGH THE MIDDLE OF THE PARK. NOT POSING ANY DANGER
2028160	14/02/2022	14053	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Mountain Road PK000878	TREE ON THE BERM VERG HAS BLOWN OVER ONTO THE PROPERTY OF 9 MOUNTAIN ROAD AND DAMAGED A GAZEBO, LAWN AND ALSO A FISH TANK. GORDON WOULD LIKE A CALL. TREE ISNT ANY IMMEDIATE DANGER PASSED 1307 9 Mountain Road – Tree fallen over property, cut away from property and chip debris.
2038658	18/02/2022	14140	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Wright Park PK000218	94 PANDORA AVENUE -BETWEEN RETAINING WALL AND THE CREEK - ACCESS THROUGH 94 PANDORA BIG TREE FALLEN OVER THE CREEK
2027427	14/02/2022	14045	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Sala Street/Puarenga Reserve PK000129	OUTSIDE 99 SALA STREET TREE HAS FALLEN DOWN ON THE FOOTPATH - SEMI LARGE TREE - HASNT FULLY FALLEN OVER YET BUT CLOSE . ITS OVER THE FOOTPATH AND A SIGN
2028360	14/02/2022	14055	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Bell Road Drainage Reserve PK000542	30 BELL ROAD - BY THE CARPARK - GROVE OF TREES BY THE FENCE ON COUNCIL LAND FALLEN BIG TREE ON THE SCHOOL FENCE THE CARETAKER HAS CALLED - 027 469 3972
2128224	6/04/2022	14841	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park East Reserve PK000030	Tree fallen over (Willow) Edmond Rd entrance just down from Alison St. See attached
2030940	15/02/2022	14075	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Fairview Road Reserve PK000467	A large tree on the Fairview Reserve behind 1a Bell Road, it has fallen onto the customers fenceline

603602	Emailed	58093	Remove dead tree completed
One Note		58345	Remove, fallen branches from willows, and a dead leaning birch tree over walkway, plus private tree at the base of birch tree. Complete.
IFx000022		58522	Removed medium willow. Removed hangers x2
Emailed		58682	Removed large Dead Douglas fir tree on edge reserve.
Emailed	588172	58687	Removal of 1 Dead willow tree. Removed large deadwood from other willow tree and weight reduced low lateral limb with delamination near base. Chipped snapped out limb from liquidambar which is yet to be removed.
WD-64450	60667:	58717	Reserve too wet to enter by truck, 4wd ute used Fallen tree removed from site. Longwood cut into firewood. Debris located near the aquatic center carport, kuirau Park side along aquatic center fenceline.
WD-64584		58935	Removed failed tree from fence and took photos
607281		58940	Removed tree over stream. Completed
607339		58949	Removed branches from fallen wattle. NOTE Trunk has been left as laying in /across waterway. Please refer to regional council for this Photo attached
607347		58951	Cleared up kahikatea tree that had fallen from reserve into school carpark. Complete. Noticed two other dead or declining trees that overhang the fence which require removal. Have attached photo
IFx000024		58978	Removed failed willow tree from drainage reserve 7.2 removal complete
607661		59024	Removed fallen and hanging limbs from willow tree off shed an fence. Completed.

2091126	16/03/2022	14551	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Mountain Road PK000878	9 MOUNTAIN ROAD - Email from M Barton - Can you please schedule in some work to do some follow up pruning and removal at this property following a stem falling down in the high winds over the weekend, see pics attached. If it can be done reasonably soon that would be great for Gordon's kids sake.
2091126	16/03/2022	14551	Tree Removal - <5m Ht	1	Mountain Road PK000878	9 MOUNTAIN ROAD - Email from M Barton - Can you please schedule in some work to do some follow up pruning and removal at this property following a stem falling down in the high winds over the weekend, see pics attached. If it can be done reasonably soon that would be great for Gordon's kids sake.
2091126	16/03/2022	14551	Tree Removal - <5m Ht	2	Mountain Road PK000878	9 MOUNTAIN ROAD - Email from M Barton - Can you please schedule in some work to do some follow up pruning and removal at this property following a stem falling down in the high winds over the weekend, see pics attached. If it can be done reasonably soon that would be great for Gordon's kids sake.
2091126	16/03/2022	14551	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Mountain Road PK000878	9 MOUNTAIN ROAD - Email from M Barton - Can you please schedule in some work to do some follow up pruning and removal at this property following a stem falling down in the high winds over the weekend, see pics attached. If it can be done reasonably soon that would be great for Gordon's kids sake.
2043435	22/02/2022	14176	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Stormwater easement beside 1 Kerswell Terrace P10976	to Michael.Barton@rotorualc.nz The Liquidambar is located on a stormwater easement and has dropped branches in the recent winds last weekend. Tree has a history of branch failures and needs to be removed. Please remove Liquidambar and clean up branches that had fallen out.
2043435	22/02/2022	14176	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Stormwater easement beside 1 Kerswell Terrace P10976	to Michael.Barton@rotorualc.nz The Liquidambar is located on a stormwater easement and has dropped branches in the recent winds last weekend. Tree has a history of branch failures and needs to be removed. Please remove Liquidambar and clean up branches that had fallen out.
2043535	22/02/2022	14177	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Haynes Crescent PK000675	23 HAYNES CRESCENT - Completely dead cherry to be removed. Customer can also bring out the dead branches that he has moved from the path to be chipped too. Updated in collector Caller informed
2052473	25/02/2022	14260	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Remove dead Kowhai tree in Government Gardens. 20 minute job with chipper
2058034	1/03/2022	14308	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	5	Jackson Park PK000007	Weed species Removal, large Gums in middle, entrance clearance by 5 McDowell

Email - M Barton	59113	Removal and Reduction of specified trees on roadside bank at no 9 Mountain road.
Email - M Barton	59113	Removal and Reduction of specified trees on roadside bank at no 9 Mountain road.
Email - M Barton	59113	Removal and Reduction of specified trees on roadside bank at no 9 Mountain road.
Email - M Barton	59113	Removal and Reduction of specified trees on roadside bank at no 9 Mountain road.
607021	59309	Removed tree complete
607021	59309	Removed tree complete
608266	59356	Chipped branches, removed dead tree Completed. Stump left to grind at 23 Haynes crescent.
IFixit000031 - 210:59434		
One Note	59609	Began clearing weed species from under canopy of Large Eucalyptus in the centre of Jackson park. Removed and poisoned ivy from around base. Units to be added tomorrow.

2058034	1/03/2022	14308	Tree Removal - <5m Ht	5	Jackson Park PK000007	Weed species Removal, large Gums in middle, entrance clearance by 5 McDowell
2058034	1/03/2022	14308	Tree Removal - <5m Ht	10	Jackson Park PK000007	Weed species Removal, large Gums in middle, entrance clearance by 5 McDowell
2058034	1/03/2022	14308	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	5	Jackson Park PK000007	Weed species Removal, large Gums in middle, entrance clearance by 5 McDowell
2058034	1/03/2022	14308	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Jackson Park PK000007	Weed species Removal, large Gums in middle, entrance clearance by 5 McDowell
2099487	21/03/2022	14610	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Aquarius Drive PK000508	39a Aquarius drive - dead tree removal. See attached
2080290	11/03/2022	14475	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	4	Boielle Park Reserve PK000169	Crown lift 1 x willow tree to allow mower access
2085950	14/03/2022	14513	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	4	Rotorua Cemetery PK000963	
2085950	14/03/2022	14513	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rotorua Cemetery PK000963	
2085950	14/03/2022	14513	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	10	Rotorua Cemetery PK000963	
2085950	14/03/2022	14513	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rotorua Cemetery PK000963	
2454592	17/10/2022	17354	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Mauku Street PK000841	21 Mauku St - Michael.Barton@rotorualc.nz Please remove 3 medium sized Sycamore's growing through or adjacent to the LV powelines coming to the house. The section of property they are growing on is designated road. Trees are in collector.
2321148	4/08/2022	16313	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Lytton Street PK000807	67 LYTTON STREET - Remove declining rhododendron tree,
2103141	23/03/2022	14633	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Otaramarae Reserve PK000082	Tree has fallen over
2102940	23/03/2022	14631	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Tree down blocking road and footpath Motutara Point
2103341	23/03/2022	14636	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Devon Street West Reserve PK000458	Two large hangers in Papwaka Kowhai carpark across the street from Stadium. See attached
2121051	1/04/2022	14788	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Wylie Street PK001133	Cont. from March 2022 - Reduce all trees in the street to match the height of the trees on the side of the street with power lines. Trees next to the power lines are not to be reduced. Also see collector as Michael B has updated it.
2107300	25/03/2022	14669	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Tarewa Road PK001023	

One Note	59609	Began clearing weed species from under canopy of Large Eucalyptus in the centre of Jackson park. Removed and poisoned ivy from around base. Units to be added tomorrow.
One Note	59609	Finished removing weed species from sub canopy and ivy from large Eucalyptus, Lots of work left to be done In reserve however top side is clear and site safe
One Note	59609	Finished removing weed species from sub canopy and ivy from large Eucalyptus, Lots of work left to be done In reserve however top side is clear and site safe
One Note	59609	Finished removing weed species from sub canopy and ivy from large Eucalyptus, Lots of work left to be done In reserve however top side is clear and site safe
Emailed	60136	7.2 Removed dead standing tree outside of number 39a Aquarius drive as per instructions. Job complete
Emailed	60247	Crown lift willow for mower access. Dead wood willow and remove cherry trees growing up through willow. Mulch on site.
Ph call	60366	Removed clump of 4 self seeded wattle
Ph call	60366	Felled and chipped wattles in back of reserve bordering industrial area.
Ph call	60366	Felled and chipped wattles in back of reserve bordering industrial area.
Ph call	60366	Removed medium failed wattle from within the Crem. 7.2
608996	60459	Removed 1 x phebalium that had failed 3 x existing phebalium to remove- not urgent
610803 631729	60552	Removal of dead rhododendron. Stumpgrinding needed
613247	60748	Removed fallen tree. Complete
IFx000006	60753	Removed fallen tree. Complete.
IFx000013	60764	Removed large split out leader from Red maple tree in back of reserve opp stadium. Firewood cut and left onsite. Job complete
		NOTES Tree has poor form and multiple inclusions and historic failures.
	60826	
Ph call	60860	Small dead tree removal complete. 1 x Stump here

2116082	30/03/2022	14749	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rotorua Cemetery PK000963	
2206382	27/05/2022	15441	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Wright Park PK000218	Cont. from March 2022 - Willow tree has fallen behind 82 Pandora Ave
2206684	27/05/2022	15443	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rotorua Cemetery PK000963	
2206684	27/05/2022	15443	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Rotorua Cemetery PK000963	
2206684	27/05/2022	15443	Tree Removal - <5m Ht	2	Rotorua Cemetery PK000963	
2206684	27/05/2022	15443	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	15	Rotorua Cemetery PK000963	
2206684	27/05/2022	15443	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Rotorua Cemetery PK000963	
2126986	6/04/2022	14829	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Kingsley Drive PK000762	BERM OUTSIDE OF 48 KINGSLEY DRIVE CUSTOMER BELIEVES TREE IS DEAD. CUSTOMER HAS ASKED PREVIOUSLY TO THE THE TREE REMOVED. SHE IS HAPPY TO NOT HAVE A TREE AT ALL AS LONG AS THE DEAD ONE IS TAKEN AWAY. Michael.Barton@rotorualc.nz Hi Ian Please inspect and act accordingly
2127701	6/04/2022	14837	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Browning Crescent Plantation Reserve PK000241	BERM OUTSIDE 15 AND 22 BROWNING CRS - TREES ARE DEAD - PLSE INSPECT AND ACT ACCORDINGLY
2138530	12/04/2022	14919	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Steep Street Reserve PK000160	First tree on LH side at the top of Steep St coming from Millar Road. Large Oak cracked/splitting branch The limb still needs to be removed completely or reduced significantly and the remainder of the tree needs a reduction
2255167	28/06/2022	15822	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Rotorua Stadium PK000126	Remove Liquidambar circled in red in attached photo
2518997	25/11/2022	17824	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Kawaha Point Rd PK000751	150 Kawaha Point Road - Remove dead cedar Collector updated
2396671	14/09/2022	16922	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Ngongotaha Road PK000890	Large tree overhanging the footpath - It is in the parking area on the corner Western Road and Ngongotaha Rd in the township - Updated collector for maintenance required, Needs crown lift
2187137	16/05/2022	15293	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Jean Batten Park PK000009	Remove dead Pitto
2204246	26/05/2022	15427	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Werrina Crescent Reserve PK000204	Three cabbage trees overgrown at the back of the property at 1 Werrina Crescent. This tree can be removed. Collector updated
2204246	26/05/2022	15427	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	5	Werrina Crescent Reserve PK000204	Three cabbage trees overgrown at the back of the property at 1 Werrina Crescent. This tree can be removed. Collector updated

Ph call	61086	Removed 1x 7.2 Acacia Menzii from the Crematorium
613268	61090	Tidy up fallen tree lift canopy completed
	61136	Removal of self seeded wattle trees.
	61136	Removal of self seeded wattle trees.
	61136	Removal of self seeded wattle trees.
	61136	Remove tree's as required not complete
	61136	Remove tree's as required not complete
614594	61149	Removed dead maple. Candidate for replacement, collector updated. Form pruned neighbouring tree at number 56 This street needs form pruning an collector updated accordingly.
615257	61405	Removed 2 dwad trees collector updated
616124	61652	Mulch branches clean up fallen tree blocking road miller road
Emailed	61990	7.3 removal of large liquid ambaar tree with split on the main union. All brush chipped and all wood rung up in manageable pieces except the last section of trunk. The 4m stem will either need to be rung up and ripped with a saw or removed with the digger?
614404	62009	Dismantle of Dead cedar tree using ewp. Complete. Add to stump list .
ifixit - 21042022	62012	Lift canopies throughout street completed
Emailed	62068	Removed dead pittosporum eugenides. Wood cut up and left onsite. Job complete
613194 617701	62069	Removed 6 laege cabbage trees that were growing over residents boundary
613194 617701	62069	Removed 6 laege cabbage trees that were growing over residents boundary

2166234	2/05/2022	15110	Tree Removal - <5m Ht	1	Devon Street West Reserve PK000458	Particularly behind the back sections of 188 Devon St - remove the Doug Fir (right on the edge of the undercut streambank) Red Oak to thin and side reduce and the Copper Beech to do the same. All notes are in Collector.
2170442	4/05/2022	15150	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Kenrick Road PK000754	#15 & #7 powerline clear
2616190	2/02/2023	18577	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Wylie Street PK001133	Cont. from April 2022 - Reduce all trees in the street to match the height of the trees on the side of the street with power lines. Trees next to the power lines are not to be reduced. Also see collector as Michael B has updated it.
2438343	5/10/2022	17241	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Devon Street West Reserve PK000458	Particularly behind the back sections of 188 Devon St - remove the Doug Fir (right on the edge of the undercut streambank) Red Oak to thin and side reduce and the Copper Beech to do the same. All notes are in Collector.
2171991	5/05/2022	15164	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Pullar Park West Reserve PK000103	2 locations of snapped branches along the stream. Uprooted betula to remove too please.
2172092	5/05/2022	15165	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	TREE HAS FALLEN ACROSS TRACK BEHIND BLUEBATHS JUST IN THE ENTRY OF THE TRACK TREE IS LOOSE
3014789	18/09/2023	21384	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Phillip St PK000391	Trees located on Elizabeth Street, corner of Phillip st. Lower vegetation to be completely removed and lower branch to be reduced. This will open up the area to make it safer for residents.
2185049	16/05/2022	15274	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Remove fallen Manuka behind bowling club
2361751	30/08/2022	16610	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Parawai Road PK000924	
2194720	20/05/2022	15358	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Larch Street PK000784	OUTSIDE 3 LARCH STREET FALLING TREE, IF IT COMPLTELY FALLS WILL GO ON THE HOUSE CUSTOMER HAS PUT CONES AROUND THE TREE. AND PUTTING DANGER TAPE AROUND AS WELL
2207210	30/05/2022	15447	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	General Scheduled Rates - Activities	Manuka tree fell down
2196724	23/05/2022	15376	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Waipa Road Sawmill MTB Carpark PK000236	Remove tree off the main track into the forest this afternoon. Ring up and throw wood in the bush. See pic for location
2204146	26/05/2022	15426	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Balwyn Ave Drainage Reserve PK000526	6 BALWYN AVE - Medium size dead tree fallen in garden See resident at number 8
2204146	26/05/2022	15426	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Balwyn Ave Drainage Reserve PK000526	6 BALWYN AVE - Medium size dead tree fallen in garden See resident at number 8
2203844	26/05/2022	15423	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Owhata Road PK000914	11A Owhata Road - removal
2207310	30/05/2022	15448	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	General Scheduled Rates - Activities	Remove trees identified by Jenny as needing immediate attention along the boardwalk across the thermal lake Cnr Ranolf & Lake Rds
2206584	27/05/2022	15442	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park West Reserve PK000031	Tree has fallen over by the playground
2213651	1/06/2022	15491	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Iri Irikapua Parade PK000719	45 IRIRIKAPUA PARAD - tree removal. See collector

	62299	Completed crown thin and boundary reduction of beech tree. Removed small weedy dogwood and cleared around base of oak tree. Started boundary reduction on red oak which is still to be completed.
	62301	Reduced Street trees from powerlines and road way, removed one small tree corner of campbell and kendrick. Stump to grind. Complete
609466	62444	Remove large spars completed stumps to grind
	62500	Remove large spa completed
618680	62563	Removed uprooted Betula, removed hangers and crown lifted adjacent Quercus palustris and quercus palustris with low branch throughout reserve
619022	62581	Tree removed. Job complete
613907 613907	62602	Remove vegetation cut back branch from roadside completed
	63032	Tree felled branches stacked to take to waste management green waste. Tree was leaning over car park being held up buy Pusedopanax. Site left tidy cones removed from carparks.
596840 597143 6:	63044	Lift canopies throughout street not complete
621370	63256	Remove wind blown tree not complete
Teams chat	63360	Mature Manuka had spilt in high winds remaining section felled and cut up removed from site. Truck load of branches to be removed site safe.
Emailed	63368	Tree removed. Job complete.
621529	63432	Removed 1 medium fallen tree from property and 3 other damaged trees.
621529	63432	Removed 1 medium fallen tree from property and 3 other damaged trees.
621791	63455	Removed variegated elm tree due to root loss from Footpath excavation. located outside 11b owhata road.
622120	63562	Taped off tree that has roots slightly uprooted. Not a danger. Removed branches that are a danger to public and possibly damage thermal fence. removed dead mature Manuka from opposite fence line.
IFx000176	63630	Removed dead fallen chestnut tree.
620009	63646	Removed cherry tree in decline. Job complete

2208697	30/05/2022	15453	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Ford Rd PK000351	Tree removal
2209631	31/05/2022	15459	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Foley Drive PK000350	29 Foley Drive, tree has fallen across footpath into the hedge
2903187	13/07/2023	20604	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Island View Road PK000722	FYI #46 needs to be educed from the powerlines and maintained to council spec. hot sticks required.
2340604	23/06/2022	16464	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Old Quarry Recreation Reserve PK000078	40 RUSSELL CRESCENT AT THE DRIVEWAY ENTRANCE HALF WAY UP THE DRIVE ON THE BEND fallen tree to be removed. Wood to be left on site and debris chipped.
2213551	1/06/2022	15490	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Tawavale Street PK001027	#42 cherry not unstable, but has structural defects
2226935	9/06/2022	15610	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	4	Rotorua Cemetery PK000963	
2226935	9/06/2022	15610	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Rotorua Cemetery PK000963	
2226935	9/06/2022	15610	Tree Removal - <5m Ht	3	Rotorua Cemetery PK000963	
2221219	7/06/2022	15566	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Upland Rd PK001076	48 UPLAND ROAD ON THE BERM - Medium sized maple
2221319	7/06/2022	15567	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Clinkard Ave PK000596	11 CLINKARD AVENUE - THE TREE HAS SPLIT IN HALF IT IS ON THE BERM
2422368	27/09/2022	17122	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Wai-O-Whiro Stream Reserve PK000243	Fell the trees identified during a site visit to Waiowhero Reserve as indicated by the photos in Richards email and the orange spray markings.
2422368	27/09/2022	17122	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Wai-O-Whiro Stream Reserve PK000243	Fell the trees identified during a site visit to Waiowhero Reserve as indicated by the photos in Richards email and the orange spray markings.
2422368	27/09/2022	17122	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Wai-O-Whiro Stream Reserve PK000243	Fell the trees identified during a site visit to Waiowhero Reserve as indicated by the photos in Richards email and the orange spray markings.
2422368	27/09/2022	17122	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Wai-O-Whiro Stream Reserve PK000243	Fell the trees identified during a site visit to Waiowhero Reserve as indicated by the photos in Richards email and the orange spray markings.
2422368	27/09/2022	17122	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Wai-O-Whiro Stream Reserve PK000243	Fell the trees identified during a site visit to Waiowhero Reserve as indicated by the photos in Richards email and the orange spray markings.
2242809	20/06/2022	15723	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Waitawa Place PK001090	In the centre island at the end of Waitawa Place is a Rhodo garden. One of them has broken out and needs to be removed. Refer to photo attached
2250908	27/06/2022	15784	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	Tree to remove. See lan for map. This will be scheduled in Tuesday 14 june. TREE INFRONT OF LOT 5 SECTION C SITE 16
2681037	10/03/2023	19073	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Pererika Street PK000386	#84 This tree needs to be removed asap with medium urgency. Small oak self seeded. 1 hour to complete.

Emailed	63673	Removed small dead prunus tree.
622668	63686	Removed fastigate beech tree blown over in storm.job complete
		Notes
		Requires stump removal/ stumpgrinding and reinstatement
	63688	Lift canopies throughout street not complete
621521	63691	Done as requested. Job complete.
622789	63744	Removed cherry tree with root damage from.excavations. job complete
	63753	Removed 10 wattle trees on white st boundary of reserve. Job incomplete as branches need chipping. Approx 1.5hrs to finish chipping and clean up.
	63753	Removed 10 wattle trees on white st boundary of reserve. Job incomplete as branches need chipping. Approx 1.5hrs to finish chipping and clean up.
	63753	Removed 10 wattle trees on white st boundary of reserve. Job incomplete as branches need chipping. Approx 1.5hrs to finish chipping and clean up.
623441	63982	Removed split tree completed. Stump to grind
623848	63993	Removed broken tree. One small stump at 11 clinkcard ave. And replacement kowhia required.
Emailed	64136	Remove tree's not 3
Emailed	64136	Remove tree's not 3
Emailed	64136	Remove tree's as required not complete
Emailed	64136	Remove tree's as required not complete
Emailed	64136	Remove tree's as required not complete
624509	64212	Remove damaged tree completed
623264	64290	
623826	64291	Remove tree completed

2230115	13/06/2022	15629	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Warwick Drive Reserve PK000203	Behind 12 LYNWOOD PLACE Tree branch fell and hit roof. Tree has obvious structural issues. Remove
2232373	14/06/2022	15647	Tree Removal - <5m Ht	1	Government Gardens PK000481	Manuka tree came down in winds
2261093	30/06/2022	15857	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	4	Amohia Street PK000504	Outside Unichem Pharmacy on Amohia street, Liquidambar removal to the bracing. Crane on site, work to commence at 6:40pm Wednesday 22nd June. Chip debris and take away logwood.
2280334	13/07/2022	16004	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Whitworth Road PK001122	6 Whitworth - Tree removal acmena 3 whitworth road Acmena height reduce over road - take the lowest large limb at base over road side. and tidy where needed
2304080	26/07/2022	16183	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Manuka come down along Oruawhata Drive
2304080	26/07/2022	16183	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Manuka come down along Oruawhata Drive
2285192	15/07/2022	16043	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Gemini Place PK000372	
2681137	10/03/2023	19074	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Kuirau Park PK000025	Manuka root uplift on board walk
2291009	19/07/2022	16093	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Leo Place PK000791	
2296886	21/07/2022	16128	Tree Removal - <5m Ht	1	Grand Vue Rd PK000649	
2337857	16/08/2022	16451	Tree Removal - <5m Ht	1	Chapman Place Reserve PK000313	
2345102	22/08/2022	16489	Tree Removal - <5m Ht	1	Mahanga Rd PK000809	
2354964	26/08/2022	16567	Tree Removal - <5m Ht	1	Mill Street PK000861	
2337255	16/08/2022	16442	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Bellvue Road PK000543	
2337255	16/08/2022	16442	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Bellvue Road PK000543	
2769321	28/04/2023	19740	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Amun Place Reserve PK000072	Banksia located inside Amun place reserve at the boundary, bordering 8 Hapi street. Large banksia with poor structural integrity due to large wound left by historic lower limb removal. Complete tree removal. See attached

624692	64299	Removed ribbonwood tree with structural defects.complete.
		Notes Requires stumpgrinding. X2 other older stumps located in same row also require grinding 3 in total
	64350	Cut tree up and left branches on site. Job completed.
Emailed	64601	Crane removal, liquidambar 12am - 4 am Job Complete
Ph call	65472	Remove tree as required stump to grind at no 6 completed
Teams chat	65476	Traffic management set up, remove Manuka from road, branches taken to tip on truck 133. Site safe now.
Teams chat	65476	Traffic management set up, remove Manuka from road, branches taken to tip on truck 133. Site safe now.
	65563	Lift canopies throughout street remove tree completed
Ph call	65619	
	65747	Removed on tree, pruned other stump left to grind in centre island completed
	65749	Area 2H Street tree pruning on grandvue road/vista place/Manahi avenue. Removal of dead Japanese maple outside number 1 vista place. Photo added on collector
	66051	Pruned 4x 8.1 trees and removed 1x Cherry <5m high
	66064	Pruned all conrus sp. On Street (5x 8.1) and removed one dead tree <5m One large oak tree to be maintained on Street
	66070	Maintained 1x 8.1 rhododendron and removed a dead standing rhododendron <5m tall. One very small stump to grind Job complete
	66073	Lv powerline clearance and removal of 1 tree under powerlines as specified on collector due to poor location.
	66073	Street tree maintenance of lawson cypress trees and removal of small birch in poor condition. OTHER WORKS REQUIRED Stump grinding required at 11a and 12 bellvue road .located either side of cul de sac. 1x small 1x medium
628417	654027	66093 Remove tree as required not completed

2769321	28/04/2023	19740	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Amun Place Reserve PK000072	Banksia located inside Amun place reserve at the boundary, bordering 8 Hapi street. Large banksia with poor structural integrity due to large wound left by historic lower limb removal. Complete tree removal. See attached
2581479	10/01/2023	18297	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Oakland Place PK000896	Remove small to medium tree out of garden at end of Oakland Place
2306373	27/07/2022	16203	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Duggan Drive/Moana Views PK000637	27 DUGGAN STREET TREE HAS FALLEN OVER TO THE OTHER SIDE OF A PROPERTY, POTENTIAL THE RTREE COULD FALL ONTO THE STREET LIGHT
2307498	27/07/2022	16211	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Duggan Drive/Moana Views PK000637	Dangerous split tree at 30 Duggan Drive needs immediate attention
2542888	8/12/2022	18026	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Kuirau Park PK000025	FY 2022/2023
2318151	3/08/2022	16292	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Haumoana Street Reserve No.1 PK000489	Remove fallen branch in Haumoana St Playground
2330355	10/08/2022	16392	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Murray Linton Rose Gardens PK000056	Medium liquid ambar between playground and gardens. Remove tree and chip debris, leave logwood in manageable lengths
2859870	21/06/2023	20324	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Titokorangi Drive (Longmile Road) PK000226	Stephen.Rowlands@rotorualc.nz Please fell two Robinias on Long Mille Road (one badly leaning), crown lift Coast redwoods around pedestrian entrance to redwoods via 'Cathedral' gate, also ensure frontage of woods on Forest side comply with statutory road clearances and remove major deadwood (>100mm) above walkway path. Advise UFA of proposed dates for completion (phased approach). Also: at MTB entrance on Taupo Road (Red Stage Timber area) Crown lift Alder group at entrance to woods as discussed on site.
2859870	21/06/2023	20324	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Titokorangi Drive (Longmile Road) PK000226	Stephen.Rowlands@rotorualc.nz Please fell two Robinias on Long Mille Road (one badly leaning), crown lift Coast redwoods around pedestrian entrance to redwoods via 'Cathedral' gate, also ensure frontage of woods on Forest side comply with statutory road clearances and remove major deadwood (>100mm) above walkway path. Advise UFA of proposed dates for completion (phased approach). Also: at MTB entrance on Taupo Road (Red Stage Timber area) Crown lift Alder group at entrance to woods as discussed on site.
2334119	12/08/2022	16418	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Brookdale/StreamdaleesplReserve PK000231	29 Weston Road/ Elliot Park - Fell one gum undermined by river

628417 654027 66093

Teams chat 66136 Removal of failed ribbonwood in culdesac island.

630872 66203 Recomend removal of branch on fence, and clear street light.

Phone Call 66212 Removed split albizzia tree outside 30 Duggan street. Job incomplete.

2meter high stump left to cut down.

66280 Removed dead manuka trees x3 and taken to Council dump. Job completed

629697 66525 Cut up fallen Alder tree and chipped branches.

Main trunk will need to be pulled up closer to road and cut into firewood. Stump to be cut down lower and stump grinding of rootball.

66774 Removal of box elder tree. Job complete
Stumpgrinding required.

629778 66796

629778 66796

Emailed 66939

2341234	18/08/2022	16467	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Lake Road PK000781	Uprooted tree - medium - opposite "Patrick's boutique bakery" on 49 lake road (end of revegetation area where we worked for Mari) Park on footpath - please take cones, foot bath closed and working man. Remove debris, leave firewood if there is a safe place to do so - or take it
2341434	18/08/2022	16469	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Froude Street PK000359	Remove vandalised tree on berm - #4 Froude Street
2581681	10/01/2023	18299	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Rotorua Cemetery PK000963	2 x liquidambers at Rotorua crem
2364288	31/08/2022	16633	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Kuirau Park PK000025	1 x liquidambar removal near playground chip debris and remove logwood. Need signs, cones, rigging kit
2370320	2/09/2022	16686	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Government Gardens PK000481	End of Hatupatu Drive, opposite the toilet block, in amongst the Makukas 2 x small Silver Birch Removals, 1 x medium Silver Birch removal Chip debris
2370320	2/09/2022	16686	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	End of Hatupatu Drive, opposite the toilet block, in amongst the Makukas 2 x small Silver Birch Removals, 1 x medium Silver Birch removal Chip debris
2367896	1/09/2022	16663	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Kauae Place PK000749	
2365706	1/09/2022	16645	Tree Removal - <5m Ht	3	Government Gardens PK000481	Tree removal dead mature Manuka Poly Pools storm water out let & in garden behind energy Events Centre
2367996	1/09/2022	16664	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Devon Street West Reserve PK000458	Beside 133 Springfield Road - Tree removal - Fir - Chip debris - leave logwood
2370220	2/09/2022	16685	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Larch Street PK000784	6 Larch Street - Tree removal - Fraxinus - Chip Debris - leave wood
2369209	2/09/2022	16681	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Kokiri St PK000770	
2369210	2/09/2022	16682	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Stembridge Rd PK001002	

67174

Ph call	67180	Removed stem from roadside Berm 2x stumps to be ground
		Job complete
One Note	67392	Stopped to help chip large tree
Teams chat	67626	Removal of large liquidambar. Job complete.
		Stump left high as is to be carved
Teams chat	67695	Removed 2x 7.1 spars and 1x7.2 betula pendula next to footpath Job complete
Teams chat	67695	Removed 2x 7.1 spars and 1x7.2 betula pendula next to footpath Job complete
	67737	Lift canopies throughout street x1 small removal stump to grind completed
	67744	3 dead trees removed. 1 x between sudima and poly pools, 1x at the back of the bowling club and 1 at the Rave center. Job completed. Dump docket cost \$23.10.
Teams chat	67748	Done as requested, complete.
Teams chat	67749	Removed one large Fraxinus excelsior 7.3 (800mm DBH) from roadside Berm due to large wound on the stem. All debris cleared from site. Residents request replacement planting of Fraxinus excelsior in keeping with street. Please add to list One stump to grind
	67783	Lift canopies throughout street x stumps to Grind completed
	67784	Lift canopies throughout streetcompleted

2369210	2/09/2022	16682	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Stembridge Rd PK001002	
2369210	2/09/2022	16682	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Stembridge Rd PK001002	
2370017	2/09/2022	16683	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Beaumonts Road PK000538	
2386579	9/09/2022	16838	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Ngongotaha Domain Reserve PK000058	Remove 1 x Acer Pseuoplatanus chip debris leave log wood
2374717	5/09/2022	16724	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Streamdale Place PK001004	
2384194	8/09/2022	16815	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Kingsley Drive PK000762	
2388846	12/09/2022	16859	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Okona Cres PK000900	
2399153	15/09/2022	16939	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Landscape Drive PK000783	
2398853	15/09/2022	16936	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	1 x Removal @ Block 2 - Section J - Site 6 1 x Removal @ Block 2 - Section J - Site 6 1 x removal @ Block 2 - Section J - Site 7
2474395	28/10/2022	17497	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Barnard Road Reserve PK000121	Behind 11A John Road - Inspected tree, failure is imminent with the high likelihood of minor property damage. Permission from UFA to feel the tree has been granted via email. Access can only be gained by entering the property. Called customer but no reply and message has been left. I will need land owners permission to do this work.
2401211	16/09/2022	16956	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Pedlar Street PK000382	
2403785	19/09/2022	16974	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Hodgkins Street PK000697	
2406753	20/09/2022	17001	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Kamahi Place PK000743	
2403885	19/09/2022	16975	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	McCahon Drive PK000843	
2422568	27/09/2022	17124	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Augustus Earle Place PK000275	
2425585	28/09/2022	17150	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Remove dead pohutukawa next to the museum
2276668	11/07/2022	15971	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Scott Ave Reserve PK000132	Sales order that wasn't attached therefore not billed has been moved from case #62010 to this one so it can be billed
2446304	11/10/2022	17296	Tree Removal - <5m Ht	8	Lakefront Reserve PK000026	Remove and poison Pohutukawa shoot development from beneath the Lakefront board walk as viewed on site 4/10
2438548	5/10/2022	17242	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Okere Road Recreation Reserve PK000074	

	67784	Removed four dead trees, 4x stumps to grind.
	67784	Removed four dead trees, 4x stumps to grind.
	67785	Lift canopies throughout street x2remvals completed
One Note	67875	Removed tree, site clean, job complete. 1x extra large stump to grind.
	67902	Lift canopy remove tree stump to grind no 8a completed
	68021	Lift canopies throughout street completed
	68141	Lift canopies throughout street remove tree stump to grind no 13 completed
	68197	Remove tree completed stump to grind no 5
Teams chat	68346	Removal of invasive species tree (Maytenus boaria). Job complete
624298 629855	68402	Remove tree's as requested complete
	68473	1x small removal complete. 1 stump to grind out side 32 Peddler Street
	68559	Lift canopies throughout street completed stump to grind outside no 10
	68574	Pruned all street trees and removed 1x dead camilia Job complete
	68576	Trimmed trees. Completed ,two small stumps at numbers 1. And 5.
	68884	Trimmed Street trees. 1x removal. Complete. 1xstump to grind.
Ph call	68952	1xsmall removal. Completed
	69260	Pruning, 1 removal, not complete . chipping required Stump to grind,
Emailed	69274	Removed and poisoned young Pohutakawa from under boardwalk. Job complete
	69354	Removed medium cherry tree. Branches stacked and require chipping.

2438548	5/10/2022	17242	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Okere Road Recreation Reserve PK000074	
2438548	5/10/2022	17242	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Okere Road Recreation Reserve PK000074	
2439892	6/10/2022	17250	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	McIntyre Ave Plantation Reserve PK000046	Priority on the Paulownias
2444031	10/10/2022	17277	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	15	Government Gardens PK000481	Tree removal at boundary of driving range – no chipping
2444031	10/10/2022	17277	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	20	Government Gardens PK000481	Tree removal at boundary of driving range – no chipping
2444031	10/10/2022	17277	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	6	Government Gardens PK000481	Tree removal at boundary of driving range – no chipping
2449328	12/10/2022	17318	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Thackery Place PK001041	Tree Removal Betula Papifera
2476338	31/10/2022	17509	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Neil Hunt Park PK000461	
2476859	31/10/2022	17511	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rotorua Cemetery PK000963	Remove fallen tree that fell over the weekend 29/10 - 30/10
2612265	1/02/2023	18544	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Rotorua Cemetery PK000963	
2482365	4/11/2022	17567	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Fenton Street PK000345	On Fenton St outside ANZ (corner Fenton & Hinemoa Sts)
2500607	16/11/2022	17680	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Boielle Park Reserve PK000169	Eucalyptus removal
2582383	10/01/2023	18303	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Amohia Street PK000504	Rhodendron on a lean outside sport bop 1189 Amohia Street see attached
2582583	10/01/2023	18304	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Ngakuru Cemetery PK000888	938 WHIRINAKI ROAD - THE CEMETERY OPPOSITE THE NGAKURU SCHOOL HALL A LARGE TREE HAS FALLEN OVER THE GRAVEYARD - DAMAGING SOME HEADSTONES - THE TREE IS BLOCKING THE LOOP ROAD AT THE BACK
2681637	10/03/2023	19079	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Lakefront Reserve PK000026	Tree outside new toilets at Lakefront pushed over
2512884	23/11/2022	17779	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Boyes Beach Reserve PK000179	Remove 2 small fallen trees reported by Arnie
2513624	23/11/2022	17786	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Bell Road Drainage Reserve PK000542	Behind 34 Bell Road - Large tree fallen and hung up in neighbouring trees - High priority, Remove tree and Chip debris
2515129	24/11/2022	17793	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Linton Park West Reserve PK000031	BEHIND THE GULL SERVICE STATION ON EDMUND ROAD, ON THE WALKING TRACK, BETWEEN THE SERVICE STATION AND BRIDGE TREE HAS FALLEN DOWN AND BLOCKING THE TRACK
2531989	2/12/2022	17940	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Balwyn Ave Drainage Reserve PK000526	4 BALWYN AVE RESERVE - A NZ NATIVE AND HAS FALLEN ONTO THE PROPERTY AT 6 BALWYN AVE FROM THE RESERVE AT 4 BALWYN AVE AND THERE IS ALSO A TREE ON THIS RESERVE THAT NEEDS TO BE REMOVED LOOKS DEAD
2537982	6/12/2022	17986	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Neil Hunt Park PK000461	

	69354	Chip branches from cherry removal. Remove dead wine berry tree next to driveway that was marked on collector. Job complete
	69354	Chip branches from cherry removal. Remove dead wine berry tree next to driveway that was marked on collector. Job complete
	69395	Crown lifting and deadwooding of trees in McIntyre reserve.
	69434	Removal of manuka trees along driving range boundary. Incomplete
	69434	Remove tree's as required completed
	69434	Remove tree's as required completed
	69629	Removal of birch tree with trunk. Stump grinding required
	70362	Lift canopies throughout reserve remove dead tree not complete
Teams chat	70363	Chipped fallen Rhodo. Completed.
	70435	Crown lift and root pruning of large magnolia. crown lift of ash tree and rhododendron over driveway. Removal of dead pseudopanax
	70517	Removed tree. Completed
Emailed	70887	Remove tree completed
	70970	
646535	70974	
	71032	Majority of tree removed - log left standing and stump to be ground
IFx000941	71294	Remove tree's as required completed
646666	71298	Removed failed hung up beech tree using ewp. Branches chipped and wood left onsite. Complete
648058	71327	Remove tree's as required not complete appropriately 2hrs left
648439	71460	Removal of fallen pittosporum. Complete
	71683	Macrocarpa removal. Felled trunk and removed timber. Stump remaining to cut lower

2556152	19/12/2022	18118	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	13	Neil Hunt Park PK000461	Remove all exotics from bank next to drain and cut up into firewood and remove all debris
2556152	19/12/2022	18118	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	44	Neil Hunt Park PK000461	Remove all exotics from bank next to drain and cut up into firewood and remove all debris
2546747	13/12/2022	18051	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	SULPHUR POINT WALKING TRACK - FALLEN TREE ON THE WALKING TRACK SURLFUR POINT THE BRIDGE END OF THE VILLAGE GREEN. See attached
2558252	21/12/2022	18131	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Kuirau Park PK000025	Chip fallen Ash tree and remove logwood from site
3024686	22/09/2023	21481	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park West Reserve PK000031	1. Entry from Goldie Street behind Mitchel downs pub. Vere right towards gums at the end and remove snapped out tree over track that runs between gums and the sealed cycleway. 2. Entrance from Homedale St next to Kindy straight ahead remove fallen tree. Map attached
2829664	1/06/2023	20092	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Wahanga-a-rangi Crescent PK001087	
2612365	1/02/2023	18545	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Sunset Road Reserve PK000165	Opposite 58 , Dead tree removal
2612058	1/02/2023	18543	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	Lakefront Reserve PK000026	2 X Removals and 2 x crown reductions and reserve tree maintenance on remainder
2612466	1/02/2023	18546	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Waiteti Stream Reserve PK000202	Operiana st, waitete stream reserve. Tree failure.
2605805	24/01/2023	18495	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Chapman Place PK000588	4 CHAPMAN ROAD, KAWAHA POINT ROAD - TREE IS HANGING BADLY - CUSTOMER SAID THE SECOND BRANCH IS JUST HANGING THERE
2611543	31/01/2023	18538	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Pohutakawa tree down behind arts village
2611843	31/01/2023	18541	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Government Gardens PK000481	GOVERNMENT GARDENS - ORUAWHATA DRIVE - THERE IS A TREE THAT HAS BEEN UPROOTED AND IS ONLY STANDING UP BY LEANING ON A NEARBY TREE. ITS FALLING AWAY FROM THE ROAD BUT WILL NEED REMOVING
2617536	3/02/2023	18586	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	6	Depot Street Esplanade Reserve PK000402	Behind Total Span Shed - 114 Old Taupo road at the Mangakakahi Stream before it connects to the Utuhina Stream
2665780	3/03/2023	18937	Tree Removal - <5m Ht	3	Milne Road PK000862	THERE ARE THREE TREES THAT HAVE FALLEN DOWN INTO THE STORMWATER DRAIN AT 12 MILNE ROAD - CALLER ADVISED THE TREES ARE VERY CLEARLY OUTSIDE HIS BOUNDARY AND BLOCKING THE STORMWATER DRAIN AND HALF THE EXTENSION WAY OF MILNE ROAD. THE ADDRESS IS 12 MILNE ROAD, THE CUSTOMER BELIEVES IT TO BE AN URGENT REQUEST.
2751486	18/04/2023	19599	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	TREE HAS UPROOTED AND FALLEN ONTO THE GRASS AREA LOCATED ON THE CORNER OF HATUPATU DRIVE X ORUAWHATA DRIVE NEAR THE GIVE WAY SIGN. NOT BLOCKING ROAD OR ANY DAMAGE TO PROPERTY.

71852

71852

650434 650896 72334 Cleared fallen tree from track - job complete

650636 72422 Logs left onsite, and taped off, incomplete.

Felled hung up trees alo 651104 72432 Felled hung up trees along pathway. Logs left on site. Job 2, chipped debris from fallen willow. Logs cut up left on site. Pruned willow next to fallen tree. Lifted canopy for mowers to get around. Job complete

73103

Emailed 73405

73553 Bit of deadwood above edge of bike track an fences remaining. Incomplete

656018 73578

654080 73629 Removed declining sorbus from berm 7.1
1hrs chipping remaining

WD-74306 65745; 73839 Removed uprooted pobutakawa from carpark. Job complete 7.2

657387 73867 Remove tree's as required completed

657412 73873 Remove tree's as required completed

658293 74161 Uprooted tree. Liam and Fabian removing now, James and Whata will chip up on their way home.

WD-74964 65972; 74483 Completed by Ashby Tree Services.

2750271	18/04/2023	19589	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Government Gardens PK000481	1240 HINEMARU STREET - ART VILLAGE - 3 TREES ARE DOWN AND HAVE FALLEN ON THE BUILDING AND SPOUTING
2750372	18/04/2023	19590	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Walford Drive PK001093	8 WALFORD DRIVE - ON THE BERM - THE TREE IS HANGING IN THE AIR AND IS ON AN ANGLE - ROOTS HAVE UPLIFTED
2750071	18/04/2023	19587	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Mokoia Drive PK000869	NEXT TO 1A MOKOIA DRIVE - WASTE MANAGEMENT PLANT - TREE HAS BEEN DEAD FOR THE LAST 5 YEARS - HAS FALLEN DOWN AND BLOCKING THE DRIVEWAY INTO OUR WASTEWATER THING - A BIG CHESTNUT TREE
2708333	24/03/2023	19277	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Broken tree limb near footpath in GG's between playground and lakefront (near Teletubby hills) Also received Ifixit from City Clean with photos of more trees around this location (just after Toilet) that have uprooted. See attached.
2749971	18/04/2023	19585	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Government Gardens PK000481	OUTSIDE HINEMOA STREET AROUND NEXT TO THE CAMPERVAN PARK - 2 UPROOTED TREES Q> Does the problem impose any safety concerns? A> NO Q> Does the problem affect the usage of equipment/facilities? A> NO
2751586	18/04/2023	19600	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	QUEENS DRIVE - BEHIND TAMAKI TOURS - SPLIT DEAD WOOD TREE HAVING OVER POND AND HALF OVER FOOTPATH
2750672	18/04/2023	19594	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Corlett Street Reserve PK000453	LARGE OAK TREE UPROOTED AND LEANING ON ANOTHER TREE - COULD FALL FURTHER
2750872	17/04/2023	19596	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1		TREE RIGHT IN FRONT OF 9 WARWICK DRIVE - UNKNOWN OF THE TYPE BUT HAS BEEN BATTERED AROUND A BIT OF THE CYCLONE AND IS CONCERNING THE RESIDENT. CUSTOMER IS CONCERNED IT CAN POTENTIALLY FALL AND DAMAGE THE HOUSE OR PEOPLE IN THE HOUSE UPDATED 15/02/2023; ASHBY'S DROVE PAST AND TREE HAD FALLEN. ASHBY REMOVED
2664032	3/03/2023	18921	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Rotorua Aquatic Centre PK000509	FALLEN TREE AT AQUATIC CENTRE
2802172	16/05/2023	19923	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Logan St PK000799	12 Logan St. Tree is leaning towards the road - Customer is concerned about cars going past it 15/5 - CUSTOMER HAS CALLED AGAIN, IT NOW POSES A HEALTH AND SAFETY RISK. WENT THROUGH TO INFRA CORE AND THEY WILL ESCALATE THE JOB. THE TREE HAS BEEN GRADUALLY FALLING OVAER AND IT IS 1 METER OFF THE GROUND. THE TREE IS ONLY A SMALL TREE

659528 659695 IF 74486		Trees removed by Ashby Tree Services. Site cleaned up.
659534	74491	Complete by Ashby had chipped branches and cleaned up site
659562	74494	Completed by Ashby Tree Services. Tree fallen, medium priority. May get Ashby to clean this up tomorrow or thursday. Alternatively, we will clean it up friday
IFx001243 660197 74509		Removed two fallen pohutakawa trees behind playground toilets. Stumps need cutting down to complete
659738	74537	Completed by ashby tree services.
659750	74539	Completed by Ashby Tree services.
659761 659945 6 74541		Completed by Ashby tree services. Tree uprooted in reserve. Hanging in other tree and is sturdy. Do before Friday need digger.
659522	74581	
	74617	Removed much as possible off priority area, Made tree and site safe.
661769 660426	75174	Remove damaged tree completed stump to grind

2732456	29/03/2023	19437	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Tihi Road PK001045	OUTSIDE VERGE OF 73 TIHI ROAD - Liquid ambar to be removed due to failure. Stump grinding to follow after removal. 2 man crew, climb and dismantle. Before end of March. Use tree removal unit 250-500
2685457	14/03/2023	19105	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Rotorua Cemetery PK000963	Rotorua Cemetery - Te Ngae Rd side, chip up branches that remain from fallen Gum tree
2700756	21/03/2023	19222	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Kuirau Park PK000025	Dead silver birch on field - Near pre load site for new skate park. Closest to Pukuatua St next to carpark
2689470	16/03/2023	19132	Tree Removal - <5m Ht	3	General Scheduled Rates - Activities	Remove small trees which are dying and potentially dangerous
2814680	23/05/2023	20005	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Eruera Street PK000332	Melia has died outside 1139 Eruera Street
2701058	22/03/2023	19225	Tree Removal - <5m Ht	2	General Scheduled Rates - Activities	Remove small trees from garden
2724762	31/03/2023	19387	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Takinga St PK001015	TAKINGA STREET HEADING TOWARDS THE LAKE - TREE IS DEAD AND ROTTING, BRANCHES FALLING - SAFETY CONCERN - THE DEAD BRANCHES WILL KILL SOMEONE IF THE FALL
2724762	31/03/2023	19387	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Takinga St PK001015	TAKINGA STREET HEADING TOWARDS THE LAKE - TREE IS DEAD AND ROTTING, BRANCHES FALLING - SAFETY CONCERN - THE DEAD BRANCHES WILL KILL SOMEONE IF THE FALL
2703653	23/03/2023	19250	Tree Removal - <5m Ht	2	General Scheduled Rates - Activities	Centennial Park Block 4 - Remove small trees - Split at crotch
2735156	5/04/2023	19454	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Aquarius Drive Stream Reserve PK000092	On the reserve behind the Still water Housing area, a tree has fallen over and can collapse.
2735156	5/04/2023	19454	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Aquarius Drive Stream Reserve PK000092	On the reserve behind the Still water Housing area, a tree has fallen over and can collapse.
2830905	1/06/2023	20106	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Jean Batten Park PK000009	Arawa Street/Jean Batten Park - Fell m/stemmed kowhai which stretches across bus shelter. There's a split in base of one of the stems.
3064476	17/10/2023	21807	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park East Reserve PK000030	Location: To rerea of 33b Edmund Road Tree UID: Species: Kowhai (ivy laden) Work Required: Remove tree and cut stump as low as possible before poisoning to facilitate fence erection along boundary.
2754290	19/04/2023	19623	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Sumner Street PK001006	Street tree pruning just to bring back into council spec and remove any hazards. General maint
3043085	3/10/2023	21629	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Steep Street PK001001	Fell dead Albizzia on berm to front of 18 Steep Street , grind stump, re-soil and seed by 30/05/2023

663100	75598	Removed liquidambar tree. Wood cut up and left onsite. Stumpgrinding required.
	75835	Chipped debris from wind thrown trees next to the highway
IFx001344	75864	Remove tree completed
	75906	Remove x3 dangerous dying trees within reserve
IFx001350 IFx001	75944	Removed small Melia azeradach from outside 1139 Eruera St, job complete
	76123	Remove x2 trees with declining health from garden
665560	76205	Removal of Dead poplar trees x3.branches chipped and wood cut up and left onsite. Complete
665560	76205	Removal of Dead poplar trees x3.branches chipped and wood cut up and left onsite. Complete
	76215	Block 4 - Remove x2 Maple trees along the walkway which were split at the crotch and unsafe.
667637	76721	Remove large tree not complete
667637	76721	Cut up remaining logs for firewood and stacked onsite.Tidied up site. Job complete.
		3 stumps remaining at ground level.
	76860	Remove tree as required complete stump to grind
Removed Kowhai cover 668375	76999	Felled and limbs up kowhais covered in ivoy. Cleared track, cut and stacked branches along side footpath ready to chip. Job incomplete. Revisit another day to chip debris left.
	77050	Crown lifting and general maintenance of street trees on summer street.
		Removal of Dead Melia tree outside number 13 sumner
		Task complete
Felled, chipped and rem 668516 3012085	77175	Felled, chipped and removed dead tree as required. Log wood left on site. Task complete

2868858	27/06/2023	20373	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Amohau Street Reserve PK000055	Small dead tree at rear of postie on Amahau st. 1 hr to complete.
2779520	3/05/2023	19790	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Mamaku Domain Reserve PK000035	Work Required: Remove 2 rhodos to front of skateboard park on Karamu Street. Also lift Tasmanian blackwood to give camera view of Toilet block
2849558	15/06/2023	20240	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Ti Street PK001048	Ti street tree removal outside mitsubishi.
2763238	21/04/2023	19692	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Memorial Drive PK000853	Two conifers next to the Memorial drive walls are in decline to be removed. See attached. Contact Paul Tully for location if needed. (two conifers either side of the remembrance walls)
2817270	24/05/2023	20018	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Mauku Street PK000841	30 Mauku Street Remove rotten tree Site visited 24/4, UFA spoke with caller and agreed complaint refers to partially dead tree closer to road. Further dead/dying tree within deer fence to be left. ALL TREE RESIDUES FROM THIS FELLED TREE TO BE REMOVED FROM SITE - LEAVE ANYTHING BEYOND THE DEER FENCE. WI23.000010 ISSUED
2778145	3/05/2023	19785	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	70 Vaughan Rd (Internal All)	May 2023 - Infracore work: Internal meetings, yard work, computer work etc
2829453	31/05/2023	20090	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Government Gardens PK000481	PATHWAY BETWEEN ARTS VILLAGE& POLY POOL CARPARK OVERGROWN TREE, OVERHANGING ONTO THE PATH
2781077	4/05/2023	19800	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Brunswick Drive PK000566	
2795350	12/05/2023	19886	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	General Scheduled Rates - Activities	Remove x2 dead Birch trees
2795650	12/05/2023	19888	Tree Removal - <5m Ht	2	General Scheduled Rates - Activities	Remove x2 dead trees
2817470	24/05/2023	20020	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Okona Cres PK000900	11 OKONA CRESCENT - DEAD TREE ON THE BERM - IS A HAZARD AS WILL FALLOVER ONTO THE ROAD
2818278	25/05/2023	20027	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Remove leaning Kowhai
2852531	16/06/2023	20263	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Fenton Street PK000345	Devonwood manor motel 316 Fenton street- Crown lifting of all cedars overhanging driveway at motel, remove 1 x medium cherry. Also maintain street trees on Marguerita street outside the Devonwood manor motel. Ian to be on site and explain job details to crew
2834403	2/06/2023	20130	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Various Rotorua (Open Spaces)	See attached
3133222	28/11/2023	22350	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Lake Ohakuri Reserve PK000065	Fallen tree needs removing to allow mowers to mow this area. See attached

669595	77326	Small dead tree at rear of postie on Amahau st. 1 hr to complete.
		Not currently a risk to public but after s the aesthetics of the area.
		Please create job from this.
Job Ref: 23.00000 77363		
	77414	
	77484	
666542	77571	Remove tree as required completed
	77628	Removed large banksia tree from reserve, all wood cut up and left on site - 2man crew to return once wood has been picked up to do final clear-up of debris.
671390	77863	Clean up storm damaged trees completed
	77894	Lift canopies throughout street not complete
	78106	Remove x2 Birch trees @250mm at Heaphy Place cul-de-sac.
	78125	Remove x1 Rhododendron and x1 Pseudopanax arboreus
674009	78538	Tree and debris removed only Stump remaining
674064	78632	Removed small Kowhai from one of the seat tubs at Jean Batten square, it had broken roots and been re staked a couple of times already, will replace with a new tree this winter
	78849	Performed boundary reduction on cedar trees next to devonwood manor. 4hrs left to complete job and otherworks as outlined by ian
	78928	Pollard tree remove dead tree lift canopies over driveway all completed
Fallen tree removed as ; IFx001583	79265	Removed fallen tree as required by council. Chipped debris and left log wood on site. Job complete

2896969	11/07/2023	20555	7.3 - Tree Removal - 500mm dia @dbh or 20m - 30m Ht	1	Okareka Hall Reserve PK000068	Site: Okareka Hall Reserve Tree Location: Along fenceline with 69 Okareka Loop Road Tree UID: 0 Species: Cryptomeria japonica Work Required: Fell to ground level - tree has conflict with fenceline and chimney of house beneath canopy. Cut stump level and low as possible.
2916779	21/07/2023	20693	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Inverness Road PK000717	
2916579	24/07/2023	20691	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Roosevelt Road PK000959	
2929322	31/07/2023	20774	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Leslie Ave PK000792	
2929322	31/07/2023	20774	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Leslie Ave PK000792	
3034528	28/09/2023	21558	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Keith Road Reserve PK000019	Cabbage tree on the esplanade in front of 67 Mokoia Road has toppled over on to the neighbours fence and the one beside it is dead and needs to be removed
2950085	10/08/2023	20922	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Mallard Drive PK000816	
2953425	14/08/2023	20944	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Centennial Park Block 4 - Tree Removal - <5m Ht
2960431	16/08/2023	20988	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Joanne Crescent PK000733	
2966851	21/08/2023	21031	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Logan St PK000799	
2971115	22/08/2023	21060	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Te Ana Place PK??	
3015499	18/09/2023	21399	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Government Gardens PK000481	Queens drive, Govt gardens, near cottage - Large Tulip tree with amalaria to be removed
2994443	4/09/2023	21228	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	7	Lynmore Avenue PK000805	
3024373	22/09/2023	21479	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	7	Mamaku Cemetery PK000818	12 trees in Mamaku Cemetery need to be felled with assistance from pulling ropes. Once felled, side branches can be removed and then left on site for community group disposal.
3024374	22/09/2023	21484	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	Tree removal - Block 2 Section I Site 5
3024790	22/09/2023	21485	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	Tree Removal - Block 3 Section A Site 17
3024890	22/09/2023	21486	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	Tree Removal - Block 6 Section E Site 9
3024791	22/09/2023	21487	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	Tree Removal - Block 6 Section E Site 11
3024584	22/09/2023	21480	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Government Gardens PK000481	Hatupatu drive, bowling club government gardens. Remove manukas that fell onto buildings.
3034728	28/09/2023	21560	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Iles Road PK000716	
3029672	25/09/2023	21527	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Utuhina Stream Reserve PK000186	Tree work as set out by Stephen Rowlands - Utuhina bridge repairs

	80257	Tree removed. Logs left on site. To be removed
	80819	Lift canopies throughout street. Complete
	80826	Lifted canopies throughout street. Complete
street complete	81136	
street complete	81136	Pruned prunus to council expectations. Lifted canopies throughout street. 4, 17 and 7 removed. Stumps to be taken out. Complete
Felled cabbage tree as r 3006715	81174	Felled cabbage tree as required. Left debris to rot. Task complete
Street tree pruning comp	81593	Medium removal. Street complete
Block 4 - Remove x1 sm	81611	Block 4 - Remove x1 small tree
pruning complete. 2 x st	81790	Lift canopies throughout street remove tree at no 22 stump to grind completed
Pruning complete 1 x st	81952	Lift canopies throughout street remove dead tree completed
Pruning complete, 2 x st	82016	Lift canopies throughout street. Removal. Stumps to be removed. Street complete
Removed Tulip due to A	82328	Felled tree. Chipped debris. Cut log wood and left onsite. Job complete
Canopy lift throughout st	82378	
felled 7 x Gum trees, 5 r 3010179	82477	
Tree removed for replac	82536	Removed tree. Chipped debris. Stump to be removed. Complete
Removed tree for replac	82537	Put tree on the ground. Left to be chipped with appropriate weather. Incomplete.
Removed tree for replac	82538	Removed tree. Left on ground. to be chipped with appropriate weather. Incomplete. Estimate 1 hour
Removed tree for replac	82539	Tree left to be chipped. Incomplete.
Hatupatu drive, bowling	82550	Cleared area for visual as required. Job complete
Pruned trees on street lii	83411	Pruned trees on street lifting canopies throughout street. 1 small tree removal outside no 134. Street complete
Crane lifted trees. Chipp	83412	Crane lifted two trees. Chipped debris and left Log wood cut up and in reserve. Job complete

3048096	6/10/2023	21674	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	5	Mamaku Cemetery PK000818	5 trees in Mamaku Cemetery need to be felled with assistance from pulling ropes. Once felled, side branches can be removed and then left on site for community group disposal.
3286006	20/03/2024	23746	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park East Reserve PK000030	Dead rotten trees in the lynton park reserve behind 9 campbell place up in a corner. The trees need to be felled before they fall on someone
3286006	20/03/2024	23746	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Linton Park East Reserve PK000030	Dead rotten trees in the lynton park reserve behind 9 campbell place up in a corner. The trees need to be felled before they fall on someone
3296711	3/04/2024	23855	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Balwyn Ave Drainage Reserve PK000526	Location: Rear of 6 & 8 Balwyn Ave Tree UID: Species: Punga Work Required: Fell leaning/arching punga downhill of informal path to ground level, remove arisings from site. For completion before: 20/12/23
3296711	3/04/2024	23855	Tree Removal - <5m Ht	10	Balwyn Ave Drainage Reserve PK000526	Location: Rear of 6 & 8 Balwyn Ave Tree UID: Species: Punga Work Required: Fell leaning/arching punga downhill of informal path to ground level, remove arisings from site. For completion before: 20/12/23
3284033	19/03/2024	23727	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rangiuru Street PK000939	Tree Location: Left of the Ibis Hotel car park driveway Tree UID: 153001400 Species: Camellia Work Required: GSR Item No. 115 Tree removal 5-10m high to 150mm above ground level but DO NOT poison or grind stump (Coppice experiment)
3385564	10/06/2024	24723	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	7		Conifers at rear of industrial estate (behind camellias) were clipped as rest of conifer line but now lapsed. Remove all and have only camellias as boundary vegetation Part of the hedge is maintained as a clipped feature but as these are behind the camellias they have been left. As well as a risk of breakout in high winds (now they are 12m tall) they also show signs of having Seiridium canker so aren't a long term prospect.
3385564	10/06/2024	24723	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	18		Conifers at rear of industrial estate (behind camellias) were clipped as rest of conifer line but now lapsed. Remove all and have only camellias as boundary vegetation Part of the hedge is maintained as a clipped feature but as these are behind the camellias they have been left. As well as a risk of breakout in high winds (now they are 12m tall) they also show signs of having Seiridium canker so aren't a long term prospect.

Removed the remaining 3010179 83413 Felled gum trees as required. Continue with Job tomorrow. Half a day left

This job has now been c 3012829 83553 Remove 2 dead trees

This job has now been c 3012829 83553 Remove 2 dead trees

felled and cleared multip 3013732 84074 Remove trees requested

felled and cleared multip 3013732 84074 Remove trees requested

Job complete 3001761 84124

Job Completed 3014299 84240

Job Completed 3014299 84240

3385564	10/06/2024	24723	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	6		Conifers at rear of industrial estate (behind camellias) were clipped as rest of conifer line but now lapsed. Remove all and have only camellias as boundary vegetation
						Part of the hedge is maintained as a clipped feature but as these are behind the camellias they have been left. As well as a risk of breakout in high winds (now they are 12m tall) they also show signs of having Seiridium canker so aren't a long term prospect.
3385564	10/06/2024	24723	Tree Removal - <5m Ht	5		Conifers at rear of industrial estate (behind camellias) were clipped as rest of conifer line but now lapsed. Remove all and have only camellias as boundary vegetation
						Part of the hedge is maintained as a clipped feature but as these are behind the camellias they have been left. As well as a risk of breakout in high winds (now they are 12m tall) they also show signs of having Seiridium canker so aren't a long term prospect.
3059834	13/10/2023	21779	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Sunrise Avenue PK001008	
3063526	16/10/2023	21799	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	TiTokorangi Forest Park PK000260	Titokorangi Forest alongside Tarawera Road. Ian Green has details also see attached
3235914	15/02/2024	23247	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Kuirau Park PK000025	Fallen tree in old toot and whistle area. Needs removing so fence can be repaired and track can be reopened. Been there since cyclone Gabriel. See photo attached
3363960	23/05/2024	24520	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Amohia Street PK000504	Outside the Regent motel at 1191 Amohia st 2 of the Acer senekaki street trees have large splits in the trunks
						Amohia St, split acer removal, either early start or Traffic management
3076377	24/10/2023	21876	Tree Removal - <5m Ht	1	Carroll Place PK000582	
3076377	24/10/2023	21876	Tree Removal - <5m Ht	1	Carroll Place PK000582	
3108360	13/11/2023	22134	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Aquarius Drive Stream Reserve PK000092	Leaning cypress conifer formerly Seiridium infected now dying rapidly, falling limited by root plate pinned by adjacent pine plate. Fell to ground level chip foliage and ring up firewood, leave at base.
3108360	13/11/2023	22134	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Aquarius Drive Stream Reserve PK000092	Leaning cypress conifer formerly Seiridium infected now dying rapidly, falling limited by root plate pinned by adjacent pine plate. Fell to ground level chip foliage and ring up firewood, leave at base.
3402953	21/06/2024	24856	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Frank Street PK000356	27 Frank Street - Fell all veg conflicting with powerlines outside of property fence. Grind stumps and re-seed back to mowing state.

Job Completed 3014299 84240

Job Completed 3014299 84240

Remove tree as requirec 84254 Remove tree as required lift canopy completed stumps to Grind no18 -26

Removed hung up limb l 84269 Felled 2 large wattle. Chipped debris and cleared walkway. Job incomplete. 1 more day required

Tree now removed, reac IFx001829 84292 Removed snapped limb due to storm as required by council. Used hiab to lift limbs out of pond. Chipped debris and left site in tidy condition. Job complete

Job has been completec IFx001840 84492

Formative prune on acei 84537 Formative prune on acers along street. Canopy lift to council expectations. Small removal outside house no 51. Stump to be ground. Street incomplete. One more days work

Formative prune on acei 84537 Formative prune on acers along street. Lifting branches over footpath and road to council expectations, small removal outside house no 17. Stump to be ground. Street complete

Leaning cypress conifer 3016339 85066

Leaning cypress conifer 3016339 85066

Job complete 3016146 85067 Chipped pile of debris as required by council. Left site in tidy condition. Removed dead shrub from site. Left log wood onsite.

3402953	21/06/2024	24856	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Frank Street PK000356	27 Frank Street - Fell all veg conflicting with powerlines outside of property fence. Grind stumps and re-seed back to mowing state.
3100375	7/11/2023	22079	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Horoeka Street PK000703	
3100375	7/11/2023	22079	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Horoeka Street PK000703	
3111760	14/11/2023	22162	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Nikau Street PK000891	
3155153	11/12/2023	22519	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Tarawera Rd PK001020	Tree on forest boundary opp 88 Tarawera road is dead and leaning up against a neighbouring tree.
3131630	27/11/2023	22337	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Warwick Drive Reserve PK000203	Please fell to ground level one Sweet chestnut (dead) beside path. Grind stump to minimum 30cm below ground level, replace soil/chip mound with topsoil and re seed with utility grass mix.
3150683	8/12/2023	22495	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Amohia Street PK000504	Dead tree at 1199 Amohia Street - Remove tree and chip debris
3150683	8/12/2023	22495	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Amohia Street PK000504	Dead tree at 1199 Amohia Street - Remove tree and chip debris
3178288	21/12/2023	22708	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Ranolf Street PK000940	71 Ranolf Street - Please arrange to have defective maple tree removed and stump ground out to 30cm.
3178289	15/12/2023	22709	Tree Removal - <5m Ht	1	Hinemoa Street PK000695	1341 Hinemoa st - Remove tree and chip debris
3150684	8/12/2023	22496	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Manuka Crescent Reserve PK000038	
3144170	4/12/2023	22443	Tree Removal - <5m Ht	1	Memphis Place PK000854	
3145657	5/12/2023	22455	Tree Removal - <5m Ht	1	Jervis Street PK000731	
3178290	15/12/2023	22710	Tree Removal - <5m Ht	2	Eruera Street PK000332	2x dead street trees - Eruera st outside AA 1121 and cottage Flair 1129 Eruera - Remove 2 x melia outside Katsubi on Eruera street. Chip debris. Parking space will need to be coned off early morning.
3158450	13/12/2023	22550	Tree Removal - <5m Ht	1	Miller St PK000860	Directly outside 28 Miller Street, Glenholme, opposite Clinkard Ave. The tree looks like its been ringed and killed and the branches have fallen off the tree. Walkers are concerned it going to fall on someone as they have seen the branches fall off
3170032	20/12/2023	22639	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Ian Street PK000714	12 Ian Street, Magnolia Removal
3183137	8/01/2024	22760	Tree Removal - <5m Ht	1	Murray Linton Rose Gardens PK000056	Hanging branch over road and low branches over footpath

Job complete	3016146	85067	Chipped pile of debris as required by council. Left site in tidy condition. Removed dead shrub from site. Left log wood onsite.
Crown lifting and form pi		85236	
Crown lifting and form pi		85236	
Pruned acer palmatum ε		85422	Pruned acer palmatum along street to council Expectations. Lifting branches over road and footpath. One small removal outside no 11, stump to be ground. Power line clearance on 10 acers along street. Street complete
Climbed and removed u		85704	Climbed and removed uprooted larch as required by council. Chipped debris and left log wood on site. Work site tidy condition. Job complete.
large dead chestnut tree 3017842		85978	Felled sweet chestnut as required by council. Left stump to 1m high. Chipped debris and left site tidy. Moved Log wood off the track for clearance. Still large logs. Task completed
Removed dead rotodent IFx001903		86032	Removed dead rotodentrum outside 1199 as required by council. Chipped debris and left site in a tidy condition. Removed log wood from site. Task complete
Removed dead rotodent IFx001903		86032	Removed dead rotodentrum outside 1199 as required by council. Chipped debris and left site in a tidy condition. Removed log wood from site. Task complete
tree removed. Stump tr 3017269		86055	Felled and removes dead tree required by council. Chipped debris and left site clean and tidy condition. Left log wood onsite. Job complete
job complete IFx001908		86437	Removed split maple tree as required by council. Chipped debris and left site in tidy condition. Removed log wood from site. Stump to be ground. Job complete.
General reserve maint.		86483	Lift canopies and deadwood on oaks and birch throughout reserve as required by council. Lifting branches over road and clearance. Task incomplete. Few more days work left. Felled dead prunus in reserve. Chipped debris and left site in tidy condition. Left log wood on site.
Formative prune on tree		86503	Formative prune on treea along street. Lifting branches over road and walkway. 1 small removal outside no 1. Street complete
Pruned and deadwood c		86531	Pruned and deadwood cypress to council expectations. Lifting branches over the road and walkway. 1 small removal outside house no 21. Street incomplete. 1 more days work.
Removed two dead meli IFx001921		86541	Removed two dead melia trees as required by council. Chipped debris and left site in tidy condition. Took log wood from site. Cut stumps to ground level. To be ground. Job complete.
Removed dead tree as r 3020317		86714	Removed dead tree as required by council. Cut stump to ground level. To be stump grinded. Left site in tidy condition. Job complete
tree removed. job compl		86750	Remove tree as required not complete
completed crown lift aroi IFx001964		87134	Crown lift on oaks throughout reserve. Clearance for mowers and pedestrians. Clearance for trucks. Job incomplete. Estimate 2 weeks work.

3360329	20/05/2024	24478	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Werrina Crescent Reserve PK000204	44 Shirley Street - Reserve tree, row of 5 large conifers.
3360329	20/05/2024	24478	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	Werrina Crescent Reserve PK000204	44 Shirley Street - Reserve tree, row of 5 large conifers.
3360329	20/05/2024	24478	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Werrina Crescent Reserve PK000204	44 Shirley Street - Reserve tree, row of 5 large conifers.
3188895	11/01/2024	22817	Tree Removal - <5m Ht	1	Old Te Ngae Rd PK000902	Fallen tree limbs at 14 Te Ngae road outside Tui House
3194905	16/01/2024	22884	Tree Removal - <5m Ht	2	Neil Hunt Park PK000461	3 x dead and declining trees to be removed at Neil hunt park. Photos attached
3194905	16/01/2024	22884	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Neil Hunt Park PK000461	3 x dead and declining trees to be removed at Neil hunt park. Photos attached
3198628	18/01/2024	22915	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Elizabeth Street PK000325	18A Elizabeth Street - Tree has fallen down on the berm and is covering the footpath
3219062	2/02/2024	23100	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Linton Park West Reserve PK000031	2 x trees down paralell to Edmund Road in the reserve.
3353357	16/05/2024	24426	Tree Removal - <5m Ht	1	Ford Rd PK000351	
3245553	22/02/2024	23345	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Neil Hunt Park PK000461	Remove fallen Rhododendron from toilet block garden
3206025	23/01/2024	22976	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	King St PK000763	Please carry out removal of two trees outside 17 King Street. Fell to ground level only - stump to be removed by roading contractor. Work within TTM of roading contractor.
3206025	23/01/2024	22976	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	King St PK000763	Please carry out removal of two trees outside 17 King Street. Fell to ground level only - stump to be removed by roading contractor. Work within TTM of roading contractor.
3245453	22/02/2024	23341	Tree Removal - <5m Ht	1	Lakefront Reserve PK000026	nfracore staff have identified a Totara tree that has died at the Lakefront. The garden team are happy to remove the tree rather than task the arboriculture team to do this job.
3248002	23/02/2024	23369	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Glenholme Reserve PK000479	Clean up after limb failure. See attached
3207489	24/01/2024	22992	Tree Removal - <5m Ht	6	Hamurana Reserve PK000484	
3207489	24/01/2024	22992	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Hamurana Reserve PK000484	
3207489	24/01/2024	22992	Tree Removal - <5m Ht	6	Hamurana Reserve PK000484	
3207489	24/01/2024	22992	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Hamurana Reserve PK000484	

Closed for billing this mc 3023003	87357	Felled cypress as required by council. 3 out of 5. Chipped debris and left log wood on site. Task incomplete. Estimate 2 more days work.
Closed for billing this mc 3023003	87357	Climbed and cleared branches from cypress in preparation for hiab job. Chipped debris and left site in tidy condition. One more days of work to be done. Job incomplete.
Closed for billing this mc 3023003	87357	Climbed and cleared branches from cypress in preparation for hiab job. Chipped debris and left site in tidy condition. One more days of work to be done. Job incomplete.
job complete 3023455	87463	Chipped and removed snapped tree as required by council. Left site in tidy condition. Task complete
Felled and removed thre	87467	Felled and removed three dead dying trees in reserve as required by council. Chipped debris and left log wood on site. Stumps to be ground and removed. Task complete.
Felled and removed thre	87467	Felled and removed three dead dying trees in reserve as required by council. Chipped debris and left log wood on site. Stumps to be ground and removed. Task complete.
Removed failed limb off 3024241	87686	Removed failed limb off tree as required. Removed entire tree due to future failure. Chipped debris and left site in tidy condition. Left log wood onsite. Task completed
2x trees removed. job cc	87701	Removed two fallen trees as required by council. Chipped debris and left site in tidy condition. Task complete
Work complete. Powerlir	87731	Pruned prunuses to council expectations. Lifting branches over road and footpath. Cleaned epicornic growth on base of tree. Left trees in powerlines as too dangerous. Small removal of epicornic shoots from old stump. Stump to be ground. Chipped small debris from reserve side. Street incomplete. All trees left in powerlines remain.
Remove large fallen Rhc	87763	Remove large fallen Rhododendron tree from garden at toilet block and cart to landfill. Landfill charges = \$22.00 + mark-up
2x trees removed. job cc 3024824	87902	Removed last of branches left on tree log wood remaining. Chipped debris and left log wood on site. Task incomplete. 1 more days work. One medium removal, strawberry tree. Chipped debris and left log wood onsite. Stump remaining
2x trees removed. job cc 3024824	87902	Climbed and removed remaining log wood from tree. Cleared log wood from site. Left site in tidy condition. Stump to be ground. Task complete
Cut down and removed 3024868	87924	Cut down and removed one small dead totara from Lakefront lawn area.
	87954	Remove tree
Job closed for billing, ple	88009	Maintained tree along reserve as required by council. Lifting canopies for clearance from footpath. Dead tree removals small to medium in size. Left site in tidy condition. Task incomplete. Estimate 1 weeks worth of work.
Job closed for billing, ple	88009	Maintained tree along reserve as required by council. Lifting canopies for clearance from footpath. Dead tree removals small to medium in size. Left site in tidy condition. Task incomplete. Estimate 1 weeks worth of work.
Job closed for billing, ple	88009	Dead tree removals ranging from small to medium size. Chipped debris and left site in tidy condition. Job incomplete. Few more days work.
Job closed for billing, ple	88009	Dead tree removals ranging from small to medium size. Chipped debris and left site in tidy condition. Job incomplete. Few more days work.

3207489	24/01/2024	22992	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Hamurana Reserve PK000484	
3338997	6/05/2024	24294	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Reporoa Domain Reserve PK000114	Remove dead tree. See attached pic
3347296	10/05/2024	24371	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Hamurana Road PK000660	994A Hamurana Road - Please fell Japanese walnut (which encroaches dwelling) within road berm on western side of house to ground level and poison stump/s. Stack all stemwood inside Council land unless caller wants firewood. All branch arisings to be chipped and removed from site. Please ensure site is left clean and tidy. Map attached
3347092	10/05/2024	24369	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Scott Ave PK000979	Behind 9a Elliott Crescent - Infracore work request: Please remove trees 2 and 3 and poison stump as these are within the reserve. Do NOT address tree no 1 as it is privately owned. GSR rates apply. Please note sewer route and avoid if straight felling. Remove all debris as this is a school area
3248102	23/02/2024	23370	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Neil Hunt Park PK000461	Small tree down. Reported by mower operators. Pic attached
3236985	16/02/2024	23262	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Remove dead silver birch sudiuma x 2
3240018	19/02/2024	23290	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Fenton Street PK000345	319 Fenton Street - Tree is completely dead - Out the front of Ace Motor lodge
3240018	19/02/2024	23290	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Fenton Street PK000345	319 Fenton Street - Tree is completely dead - Out the front of Ace Motor lodge
3240019	19/02/2024	23291	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Hinehopu Reserve PK000492	On the 3rd February a mini tornado whipped through & fully uprooted quite a large tree in the Hinehopu Reserve. Apparently it is lying along the grass, closest to the lake side (not over the road). The root ball is out of the ground too, so there will be ground reinstatement required.
3343178	8/05/2024	24339	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Old Quarry Road Plantation Reserve PK000288	Behind 22A Old Quarry Road - 2 x trees to remove. 1 x juglans (walnut) 1 x dead tree covered in ivy. Work from reserve side, chip debris, leave wood.
3254924	28/02/2024	23437	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Karamu Street PK000746	Several trees require to be crown lifted well ahead of Mamaku Car Show on 16th March 2024. Detail to be discussed with UFA/Ian Green prior to commencement.
3254924	28/02/2024	23437	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Karamu Street PK000746	Several trees require to be crown lifted well ahead of Mamaku Car Show on 16th March 2024. Detail to be discussed with UFA/Ian Green prior to commencement.
3242628	21/02/2024	23315	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Boyes Beach Reserve PK000179	Remove leaning tree with root plate lifting in playground
3248203	23/02/2024	23371	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Lynmore Avenue PK000805	50 Lynmore Ave Tree hit by car, tree destroyed needs to be removed
3318273	17/04/2024	24072	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Kuirau Park PK000025	Dead oak tree sportsfield. Mature tree

Job closed for billing, ple	88009	One large removal over footpath and road. EWP. Chipped debris and left site in tidy condition. Left log wood on site. Reserve incomplete. Estimate a weeks worth of work
job complete	88017	Removed two dead prunus in park. Chipped debris and left site in tidy condition. Cut stump to ground level. Stumps to be ground and removed. Complete
3007284	88311	Climbed and removed what was left to do. Chogged stemwood down and left on reserve side over the fence. Log wood left on site. Task complete.
Job complete	3025998	88391 Felled and removed two trees in ivy as required by council. Spoke to home owner about private tree and told her it was over the fence line. Chipped debris and left site in tidy condition. Task complete.
	88700	Remove fallen tree completed
Dead Silver birch remov	88736	Dead Silver birch removed from the rear of the Sudima. Green waste to tip. Job completed.
3027682	88838	Remove dead tree's as required
3027682	88838	Remove dead tree's as required stumps to grind
3027869	88879	Tidy up fallen tree
job complete	3027873	88880
	3028061	88908 Lift canopies remove trees as required
	3028061	88908 Lift canopies remove trees as required
	89171	Remove dead tree as required completed
	89192	Removed tree and Removed stump reinstate completed.
Job complete	IFx002075	89279 Removed large dead oak tree as required by council. Chipped debris and left site in tidy condition. Left log wood on site. Cut stump down to council expectations. Stump to be ground. Job complete

3441711	29/07/2024	25208	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Linton Park West Reserve PK000031	Tree branch is split over a mown track. Tree branch split over mown track . Over stream and to the right of the vehicle bridge that ws taken out. Photos
3441711	29/07/2024	25208	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park West Reserve PK000031	Tree branch is split over a mown track. Tree branch split over mown track . Over stream and to the right of the vehicle bridge that ws taken out. Photos
3441711	29/07/2024	25208	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Linton Park West Reserve PK000031	Tree branch is split over a mown track. Tree branch split over mown track . Over stream and to the right of the vehicle bridge that ws taken out. Photos
3273117	12/03/2024	23621	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	4	Jackson Park PK000007	RFS details: Pivot tree is in flower Jackson Park near the McDowell Street entrance causing significant hayfever issues with neighbouring properties. Action request from Gary Coker ; There is a chinese privet above the hydrangers and a flowering tree privet above the cotoneaster, please remove both the privets, poison the stumps and the team can remove the cotoneaster as well
3273117	12/03/2024	23621	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Jackson Park PK000007	RFS details: Pivot tree is in flower Jackson Park near the McDowell Street entrance causing significant hayfever issues with neighbouring properties. Action request from Gary Coker ; There is a chinese privet above the hydrangers and a flowering tree privet above the cotoneaster, please remove both the privets, poison the stumps and the team can remove the cotoneaster as well
3266504	8/03/2024	23542	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Lake Tikitapu Reserve PK000147	Inspect large tree that has fallen on reserve for removal
3271213	12/03/2024	23603	Tree Removal - <5m Ht	2	General Scheduled Rates - Activities	Remove x2 Prunus trees
3273118	12/03/2024	23622	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	McIntyre Avenue Reserve PK000045	Reserve tree maintenance. Multiple failed limbs. Crown lift. Dead wood.
3273118	12/03/2024	23622	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	McIntyre Avenue Reserve PK000045	Reserve tree maintenance. Multiple failed limbs. Crown lift. Dead wood.
3288990	25/03/2024	23780	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Gillam Crescent Espl Reserve PK000476	Tree on track from Brook PI to Utuhina Rd corner . see attached
3325197	23/04/2024	24145	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Ray Boord Park PK000112	Removal of 2 cedar trees by the toilet blocks
3325197	23/04/2024	24145	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Ray Boord Park PK000112	Removal of 2 cedar trees by the toilet blocks
3325197	23/04/2024	24145	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Ray Boord Park PK000112	Removal of 2 cedar trees by the toilet blocks

Job complete	IFx002087	89460	Removal of cherry tree and black walnut near fence line. Chipped debris and left site in tidy condition job incomplete. One more cherry and small privit to remove. One more days work left
Job complete	IFx002087	89460	Removal of cherry tree and black walnut near fence line. Chipped debris and left site in tidy condition job incomplete. One more cherry and small privit to remove. One more days work left
Job complete	IFx002087	89460	Removal of cherry tree and black walnut near fence line. Chipped debris and left site in tidy condition job incomplete. One more cherry and small privit to remove. One more days work left
Remove tree's as requin 3026739		89585	Remove tree's as required
Remove tree's as requin 3026739		89585	Remove tree's as required
		89831	Clear vegetation from gateway
Remove x2 Prunus trees		90078	Remove x2 Prunus trees along drain, rough mulch & poison stumps. 1 bottle cut n paste poison
various dead wood and i		90129	
various dead wood and i		90129	
Work completed as per c		90193	Removed medium dead tree on Gillam Ave, found and cleaned up fallen tree in reserve.
		90240	Felled 1 of two ceders as required by council. Chipped debris and left site in tidy condition. Left log wood on site. Use of machine to remove logs. Task incomplete further work required.
		90240	
		90240	

3292975	27/03/2024	23816	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Rotorua Cemetery PK000963	Tree failure, potential damage to headstone.
3456288	8/08/2024	25324	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Ann St PK000507	18 Ann Street - remove dead ash
3294520	28/03/2024	23828	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Sala Street/Puarenga Reserve PK000129	Remove dead gum
3294520	28/03/2024	23828	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Sala Street/Puarenga Reserve PK000129	Remove dead gum
3294520	28/03/2024	23828	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Sala Street/Puarenga Reserve PK000129	Remove dead gum
3306298	9/04/2024	23947	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Rimuvale St PK000951	
3307798	10/04/2024	23959	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Ruby PI PK000965	
3307798	10/04/2024	23959	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Ruby PI PK000965	
3356547	16/05/2024	24447	Tree Removal - <5m Ht	1	Linton Park East Reserve PK000030	Low tree branches beside Edmond road carpark entrance unable for tractor to get under, fallen tree in same area also
3449841	2/08/2024	25275	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	12	Wrigley Road Reserve PK000222	large tree branch has fallen over Wrigley road reserve bank area
3319241	18/04/2024	24080	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Union St PK001075	Removal of the middle tree (maple) outside 15 Union Street to allow Kainga Ora to get a dwelling onto the site between the 2 rhododendrons
3348945	13/05/2024	24385	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Linton Park East Reserve PK000030	Remove fallen tree. see attached
3322600	22/04/2024	24113	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Government Gardens PK000481	Please remove two dead birch trees within the EEC car park. Fell to ground level and apply poison gel to the stumps.
3327487	24/04/2024	24169	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Pukaki Street PK000401	Customer has advised that the tree that it on the corner of Pukaki street and Rangiora Street is split right down the middle. If a large amount of wind hit the tree, it would completely split and fall down. Tree is on the right-hand side of Pukaki street - near the Regent Hotel (Corner)
3333121	30/04/2024	24223	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Michael Place Drainage Reserve PK000301	Next to 67 Edmund Road - Fallen tree arrange removal with stemwood rung up/left on site
3333904	1/05/2024	24233	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Carlton Street PK000578	20 Carlton Street - Tree is dead, but not dangerous. Aiming to be removed 1st week of may 24
3338138	3/05/2024	24288	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Manahi Ave Reserve PK000037	Waiwhero Stream lake front reserve in front of 17 Gemini Place - This tree to be removed before end of this week (1st week may) access can be granted from joe +64 29 813 6260

Tree removed. Stump w		90775	Remove tree as required
Job complete	3033739	90793	Removed dead tree as required using EWP. Chipped debris and left site in tidy condition. Left log wood onsite. Felled stem in one piece. Stump to be cut down and stump ground. Task complete.
Gum tree removed and		90910	
Gum tree removed and		90910	
Gum tree removed and		90910	
Street Complete		91225	Pruned prunus to council expectations. Lifting branches over road and footpath. Canopy lift. Left street in tidy condition. Street complete.
Street complete		91228	Crown lift melias to council expectations. Lifting branches over road and footpath. 2 large removals 1 medium removals. Left log wood on site. 3 stumps to be ground. Left street in tidy condition. Street complete
Street complete		91228	Crown lift melias to council expectations. Lifting branches over road and footpath. 2 large removals 1 medium removals. Left log wood on site. 3 stumps to be ground. Left street in tidy condition. Street complete
Job Complete		91249	Chipped and removed low hanging branches from over car park and from reserve low hanging tree as required by council to allow access with tractor. Left site In tidy condition. Task complete
complete	3036396	91447	
Job complete		91538	Remove acer, stump left high, concrete in stump.
job complete		91561	Removed low hanging tree for clearance for mowers. As required by council to lift canopies on liriodendron to allow clearance for mowers. Reserve tree maintainace. Removed 1 dead willow on other side of reserve as required by council. Left reserve in tidy condition. Task complete.
Job complete	3037402	91762	Felled and removed two dead birches as required by council. Chipped debris and left site in tidy condition. Complete.
Job complete	3009697	91901	Remove split tree maple
Job complete	3037778	91934	Removed branches from fallen tree. Left log wood on site and chipped up debris. Left site in tidy condition. Task complete
job complete	3010135	91992	Removed dead tree. Chipped debris. Need to stump grind asap
Job Complete	3034147	92015	Remove large willow chip branches logs need removing

3347815	13/05/2024	24375	Tree Removal - <5m Ht	5	General Scheduled Rates - Activities	1. Remove dead conifer trees at the top of the bank along walkway A 2. Centennial Park Block 4 - Remove the closest four plants at each pedestrian crossing and use plants to gap-up other gardens. Re-mulch gardens as required.
3347815	13/05/2024	24375	Tree Removal - <5m Ht	5	General Scheduled Rates - Activities	1. Remove dead conifer trees at the top of the bank along walkway A 2. Centennial Park Block 4 - Remove the closest four plants at each pedestrian crossing and use plants to gap-up other gardens. Re-mulch gardens as required.
3346787	10/05/2024	24368	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Sala Street/Puarenga Reserve PK000129	Puarenga Stream Walkway Clean up and remove a tree that's has fallen over the walkway opposite Scott street
3363755	23/05/2024	24518	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Remove small dead tree. See attached
3358346	17/05/2024	24463	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Pukaki Street PK000401	
3363111	22/05/2024	24511	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Amohau Street PK000503	Removal of Silver Birch behind Sudima Hotel as requested by Jenny Baldwin
3361736	22/05/2024	24492	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Tarawera Rd PK001020	1. Clean up fallen tree on Tarawera Road just before Selwyn 2. Tree fallen over in BMX track
3361736	22/05/2024	24492	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	6	Tarawera Rd PK001020	1. Clean up fallen tree on Tarawera Road just before Selwyn 2. Tree fallen over in BMX track
3400210	20/06/2024	24840	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Ferguson Place Walkway PK000470	Behind 24a Old Quarry place. Detail: Can we please do a boundary clearance behind this address and remove the privet trees in preparation of a new boundary fence being constructed
3400210	20/06/2024	24840	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Ferguson Place Walkway PK000470	Behind 24a Old Quarry place. Detail: Can we please do a boundary clearance behind this address and remove the privet trees in preparation of a new boundary fence being constructed
3363860	23/05/2024	24519	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Gem Street PK000371	43 GEM STREET - Tree on verge has snapped at the trunk and is fully leaning on the tree of the neighbors. if it falls over anymore it will be fully across the road. They noticed it today but could have snapped in the bad weather yesterday.
3403829	24/06/2024	24865	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Werrina Crescent Reserve PK000204	44 Shirley Street - Reserve tree, row of 5 large conifers.
3403829	24/06/2024	24865	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Werrina Crescent Reserve PK000204	44 Shirley Street - Reserve tree, row of 5 large conifers.
3478744	26/08/2024	25518	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Manahi Ave Reserve PK000037	Tree has been deemed as hazardous, seen across the walkway area behind the property 18 Tupara Crescent
3382730	7/06/2024	24702	Tree Removal - <5m Ht	10	General Scheduled Rates - Activities	Remove dead trees within bush areas
3382730	7/06/2024	24702	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	6	General Scheduled Rates - Activities	Remove dead trees within bush areas
3382730	7/06/2024	24702	Tree Removal - <5m Ht	3	General Scheduled Rates - Activities	Remove dead trees within bush areas

Block 4 - Remove all debris	92355	Remove conifers from bank in block 4 and 1x dump truck.
Block 4 - Remove all debris	92355	Removal of 5 blaww conifers in block 4, 2x dump tickets. Harley and Gavin in peace garden releasing wine berry. Kieran away sick.
job complete	92381	Tidy up fallen gum tree
Remove dead tree in mc	92530	Remove x1 dead tree
Job complete	92739	Removed split acer in centre Parking lot. Cut limbs and chipped debris. Left site in tidy condition. Left log wood on site. Task complete
job complete	92771	Removed compromised silver birch tree behind sudima.
Job complete	92794	
Job complete	92794	
job complete	3009829	92834 Remove tree's as required
job complete	3009829	92834 Remove tree's as required
Job complete.	3009980	92898 Completed removal of failed tree, leaning on neighbors tree on Gem street.
Job complete	3023003	93008 Removed 2 last conifers from row. Cleared tree as required by council. Chipped debris and left site in tidy condition. Cut stumps to ground level. Left log wood onsite for firewood. Lifted canopies on two medium birches for clearance and deadwooded. Task complete. Stumps to be ground.
Job complete	3023003	93008 Removed 2 last conifers from row. Cleared tree as required by council. Chipped debris and left site in tidy condition. Cut stumps to ground level. Left log wood onsite for firewood. Lifted canopies on two medium birches for clearance and deadwooded. Task complete. Stumps to be ground.
complete	3011158	93121
Remove x13 small & x6	93324	Remove dead trees from bush areas
Remove x13 small & x6	93324	Remove dead trees from bush areas
Remove x13 small & x6	93324	Removal of dead trees within revegetation areas. Three were of medium size

3392106	14/06/2024	24773	Tree Removal - <5m Ht	2	General Scheduled Rates - Activities	Remove two reserve trees, poly pools x 1 Millennium x 1
3387864	11/06/2024	24742	Tree Removal - <5m Ht	5	Centennial Park PK000303	Multiple broken braqnches, hangers and tree failures throughout Park to remedy
3387864	11/06/2024	24742	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Centennial Park PK000303	Multiple broken braqnches, hangers and tree failures throughout Park to remedy
3400409	20/06/2024	24839	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Totara St PK001056	5 Totara Street - Customer advises that a car had hit this tree and now the tree is split and has concerns that it may fall over.
3395067	17/06/2024	24793	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Fenton Street PK000345	Fenton St racecourse, dead Lancewood to remove
3460675	13/08/2024	25355	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Robertson St PK000955	40 Robertson St - Phoenix palm full of pigeons causal faecal issues to neighbour at 40. Please fell to ground level and grind/re-seed stump.
3433550	19/07/2024	25134	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Steep Street PK001001	16 Steep Street - Please fell to ground level Banksia tree on front fenceline. Ensure stump is poisoned but no need to stump grind. Ring up stem wood and leave on site.
3533066	9/10/2024	26057	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Mount View Drive PK000879	9A Mount View Drive - Please remove 3-stemmed birch from fence line. Arguably a shared responsibility but Council happy to remove as birch not viable long term. Please poison stump but do not stump grind. Leave stem wood ringed up on site.
3533066	9/10/2024	26057	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Mount View Drive PK000879	9A Mount View Drive - Please remove 3-stemmed birch from fence line. Arguably a shared responsibility but Council happy to remove as birch not viable long term. Please poison stump but do not stump grind. Leave stem wood ringed up on site.
3423140	11/07/2024	25042	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Utuhina Stream Reserve PK000186	Tree is on reserve opposite No. 30 Harold Crescent. Please fell Douglas fir to ground level ahead of community revegetation project. Unsuitable for long term retention. Ring up all stem wood and leave on site. Fire chips across the area. No need to stump grind.
3423140	11/07/2024	25042	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Utuhina Stream Reserve PK000186	Tree is on reserve opposite No. 30 Harold Crescent. Please fell Douglas fir to ground level ahead of community revegetation project. Unsuitable for long term retention. Ring up all stem wood and leave on site. Fire chips across the area. No need to stump grind.
3411079	1/07/2024	24920	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	Lake Ohakuri Reserve PK000065	A mostly dead willow is split and heavily decayed internally. Has potential to fail onto the boat launching ramp. Please fell to ground level, do NOT poison or grind stump. Also fell a Lawson cypress (end of row) as it is cankered and can facilitate straight fell of willow onto reserve portion behind. Chip all branch wood and pile on site as will be reveg'd later. Ring up all stem wood and leave on site.

Two trees removed behi	93433	Cut down 2x Leptospermum copper sheen behind Millennium Hotel. Green waste to dump. Job completed.	
works here complete.	93493	Maintained reserve trees as required by council. Powerline clearance, general formative prune. Crown lift on wattles along reserve edge. Two small dead removals. Stumps to be ground. Left reserve and trees in tidy condition. Task complete on road side of park. Half of park side centennial to be completed.	
works here complete.	93493	Maintained reserve trees as required by council. Powerline clearance, general formative prune. Crown lift on wattles along reserve edge. Two small dead removals. Stumps to be ground. Left reserve and trees in tidy condition. Task complete on road side of park. Half of park side centennial to be completed.	
Job complete	3012487	93614	Remove tree as required stump to grind outside No 5
tree removed. No stump	93626	Removed dead tree as required Chipped branches	
Job complete	3012680	93733	Remove large palm tree stump grinding required
Tree removed, 1 x stum	3011440	93739	Remove tree as required Mulch branches
Remove tree's as requir	3012058	93740	Remove tree's as required signs cones chip brush poison stumps
Remove tree's as requir	3012058	93740	Remove tree's as required signs cones chip brush poison stumps
Job complete	3012850	93751	Removed Douglas fir tree as required by council. chipped debris and left a few brush left to be chipped tomorrow. Felled stem wood and left in one log. Task incomplete. One more days work to be completed. Left mulch onsite chipped into bank.
Job complete	3012850	93751	Tidy up branches and Mulch
Job complete	3012989	93769	

3435962	22/07/2024	25155	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Hinemoa Street PK000695	2 x trees to remove near 1478 Hinemoa street
3435962	22/07/2024	25155	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Hinemoa Street PK000695	2 x trees to remove near 1478 Hinemoa street
3508039	17/09/2024	25790	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Westbrook Reserve PK000205	Please remove Kanuka on Reserve side of boundary with 15b Pharoah Place. Poison stump and chip all stems
3508039	17/09/2024	25790	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Westbrook Reserve PK000205	Please remove Kanuka on Reserve side of boundary with 15b Pharoah Place. Poison stump and chip all stems
3508039	17/09/2024	25790	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Westbrook Reserve PK000205	Please remove Kanuka on Reserve side of boundary with 15b Pharoah Place. Poison stump and chip all stems
3417568	8/07/2024	24986	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Lake Okaro Reserve PK000027	Large fallen tree needs to be removed (dangerous) see attached
3430855	17/07/2024	25107	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	Hamurana Reserve PK000484	HI. Trees on Haumarana walkway need attention. One especially near the playground, on the green grass beside and near the stand of Redwoods. The chestnut tree has branches precariously hanging down by a shred from a large limb of the tree. Kids play under there. Other trees are now in the lake. Time for arborist and a clean. Up
3483588	29/08/2024	25566	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Orion Street PK000910	58 Orion Street - Fell female ginkgo and grind stump
3500964	11/09/2024	25722	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Parawai Road Esplanade Reserve PK000409	On local purpose reserve on boundary of 62A and 58 Parawai Road - Please fell spruce to ground level, DO NOT poison or grind stump. Check with occupant of No.62a if they want the logs and if not remove from site. Access via No. 62a.
3500964	11/09/2024	25722	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Parawai Road Esplanade Reserve PK000409	On local purpose reserve on boundary of 62A and 58 Parawai Road - Please fell spruce to ground level, DO NOT poison or grind stump. Check with occupant of No.62a if they want the logs and if not remove from site. Access via No. 62a.
3434572	22/07/2024	25144	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Remove Privet tree from within reserve
3434673	22/07/2024	25145	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	General Scheduled Rates - Activities	Remove Prunus tree from within reserve
3434573	22/07/2024	25146	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Pukehangi Road Garden - Remove dead Kowhai trees from within garden
3434782	22/07/2024	25147	Tree Removal - <5m Ht	4	General Scheduled Rates - Activities	Remove leaning Rhododendron tree
3432037	18/07/2024	25119	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Government Gardens PK000481	GSR July 2024

Job complete, stumps h:	93770	Removed two dead kowhai trees as required by council. Chipped debris and left site in tidy condition. Ground stumps to ground level and left soil flat to ground level. Pruned two ash trees along Amohau st crown lift and deadwood along footpath. Task complete.	
Job complete, stumps h:	93770	Removed two dead kowhai trees as required by council. Chipped debris and left site in tidy condition. Ground stumps to ground level and left soil flat to ground level. Pruned two ash trees along Amohau st crown lift and deadwood along footpath. Task complete.	
This job is complete, not 3021213	94327	Start removing trees as required	
This job is complete, not 3021213	94327		
This job is complete, not 3021213	94327		
Job complete	94348	Remove tree, lift canopies as requested. Cut up logs	
Job complete	3011348	94368	Remove large hung up branches Remove dead wood
Job Complete	3010532	94459	Medium tree. Needs to be Stump grinded. Left log wood behind, all ringed up
Job complete	3012117	94544	One large removal Cut up log for firewood Left wood at site
Job complete	3012117	94544	One large removal Cut up log for firewood Left wood at site
Remove large Privet tree	94594	Remove privet x1.	
Remove large Prunus tree	94595	Remove prunus at st Mike's, will need to be stump ground x1.	
Remove dead Kowhai tree	94596	Remove x1 kowhai.	
Remove x2 leaning Rho	94609	Remove rhododendron trees x4 possible under planting.	
Tree removals Governm	94708	Removed 3 x trees from gardens that were dead or unwanted including 2 x manuka and 1 x pohutukawa. Green waste to dump. Job completed.	

3427393	15/07/2024	25079	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Kuirau Park PK000025	Trees down across thermal fence. Also a couple that need attention in this specific area. Ash from Jenny's team is your contact on this one. Structures are trying to get in to fix the thermal fence. Directions: through the roundabout at kuirau Park, through the closed road gate. Just past the one-way narrow in the road, on the left
3427393	15/07/2024	25079	Tree Removal - <5m Ht	1	Kuirau Park PK000025	Trees down across thermal fence. Also a couple that need attention in this specific area. Ash from Jenny's team is your contact on this one. Structures are trying to get in to fix the thermal fence. Directions: through the roundabout at kuirau Park, through the closed road gate. Just past the one-way narrow in the road, on the left
3428134	16/07/2024	25082	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Pioneer Rd PK000282	
3434883	19/07/2024	25149	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Haupapa Street PK000672	Titoki on corner of Haupapa and Amohia sts by the bus stop has large split in trunk
3445838	31/07/2024	25243	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Linton Park West Reserve PK000031	Behind 7c Onyx Place remove both walnut and cherry. Grind out stumps to prevent regrowth. Not to be replanted
3445838	31/07/2024	25243	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Linton Park West Reserve PK000031	Behind 7c Onyx Place remove both walnut and cherry. Grind out stumps to prevent regrowth. Not to be replanted
3445838	31/07/2024	25243	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	4	Linton Park West Reserve PK000031	Behind 7c Onyx Place remove both walnut and cherry. Grind out stumps to prevent regrowth. Not to be replanted
3435963	22/07/2024	25156	Tree Removal - <5m Ht	1	Courtney Place PK000611	11 Courtenay Place - Council owned tree has a large split down the trunk starting at one of the major branches. Charlotte has put a ratchet strap around the trunk to hold it together and cut out a smaller branch to reduce the weight on the cracked section. I believe it is at risk of falling on to the neighboring fence and it is likely the tree will need to be cut down and replaced.
3445839	31/07/2024	25244	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Okawa Bay Reserve PK000070	Dead willow tree near toilet block/picnic bench needs felling to ground level. As marked attached to NE of picnic bench area
3478544	26/08/2024	25516	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Government Gardens PK000481	4 oak trees dead or moribund to lakeside of wai ariki spa need to be felled to ground level. Move oak stem wood around to GG log store (former compost area). Also fell 4 storm-damaged willows and remove all timber from site. Additional Location Details Area to lakeside of Wai ariki Spa
3472392	21/08/2024	25464	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Foley Drive PK000350	Remove a dying Thuja tree from garden on Foley Drive
3441303	29/07/2024	25204	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Robertson St PK000955	28 Robertson St - Small dead tree, Stump to grind

Job complete		94763	Pulled manuka out of sulphur pool as required by council. Removal all uprooted manuka in area as required. Chipped debris and left site in tidy condition. Left the log wood onsite. Task complete.
Job complete		94763	Pulled manuka out of sulphur pool as required by council. Removal all uprooted manuka in area as required. Chipped debris and left site in tidy condition. Left the log wood onsite. Task complete.
Job complete		94778	Lift canopies throughout street remove damaged tree remove dead tree's
Tree removed, Job com AC-9999		94800	Assessed tree with split trunk. Decided to remove due to trunk failure in near future. Chipped debris and left site in tidy condition. Cut stump to ground level. Plant to be replaced. Task completed
job complete	3013432	94823	Removed last cherry on retaining wall. Chipped debris and left site in tidy condition. Left log wood cut up on site. Removed several privit trees along reserve edge. Task complete.
job complete	3013432	94823	
job complete	3013432	94823	
Job complete, stump gri 3013545		95040	Removal of acer with split limbs. Cut to ground level and ground stump. Put top soil on for grass seed. Chipped debris and left site in tidy condition. Root pruned on small acer. Pruned stumps to ground level and left site in tidy condition. Task complete
Job complete	3013602	95111	Felled dead willow as required by council. Chipped debris and left site in tidy condition. Left log wood cut up onsite. Stump to be ground and grass seeded. Task complete.
Job complete	3013606	95112	Removed 2 of the large oaks required. Chipped debris and left site in tidy condition. Cut stump to ground level and collected log wood. Felled one of the two. Cut stump to required height. Task incomplete. 2 large dead oaks left to fell.
Complete		95202	Removed dead cypress as required by council and maintained deadwood from row of cypress. Chipped debris and left site in tidy condition. Task complete
job complete		95350	Remove dead tree grind stump & reinstate

3478444	26/08/2024	25514	Tree Removal - <5m Ht	25	Rotorua Cemetery PK000963	Back wall with graffiti - Remove wattle and gum trees and stump grind as we go ready for replanting.
3478444	26/08/2024	25514	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Rotorua Cemetery PK000963	Back wall with graffiti - Remove wattle and gum trees and stump grind as we go ready for replanting.
3478445	26/08/2024	25515	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	7	Rotorua Cemetery PK000963	Back wall with graffiti - Remove wattle and gum trees and stump grind as we go ready for replanting.
3494335	5/09/2024	25665	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	Tree Removal - <5m Ht	10	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	10	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	3	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444

Job complete		95363	Remove vegetation as required & grind stumps
Job complete		95363	Remove vegetation as required & grind stumps
Job complete		95363	Remove vegetation as required & grind stumps
Job complete	3007540	95372	Remove tree's qs required
Job complete	3007540	95372	Remove tree's qs required
Job complete	3007540	95372	Remove tree's qs required
Job complete	3007540	95372	Remove tree's qs required
Job complete	3007540	95372	3 large, 3 medium and 4 small trees removed from bank, chipped debris and ringed logs and left on site.

3494335	5/09/2024	25665	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	3	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	4	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	6	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	3	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3494335	5/09/2024	25665	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	12	Morey Street Reserve PK000053	The task outlined below has been assigned to you from Stephen Rowlands Comment: Please include removal of ca. 12 topped poplars on banking in Morey Street Reserve which front onto 12 Elmslie Place. It will be beneficial to pre-poison these to prevent regrowth/adventitious shoots. Prior to a native replanting scheme (To be arranged). 1444
3484564	30/08/2024	25577	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Pullar Park West Reserve PK000103	Pullar park west, dead oak tree, remove and chip debris. visible from ford road, best access from ford road.
3456806	9/08/2024	25330	Tree Removal - <5m Ht	8	General Scheduled Rates - Activities	Rotorua Stadium - Small tree removals
3455110	7/08/2024	25316	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	2	Rotorua Cemetery PK000963	Remove 5 Wattles
3459953	12/08/2024	25349	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Lakefront Reserve PK000026	2 x oak trees at lakefront near Wai-a-riki spa to remove. Stump to be ground.

Job complete	3007540	95372	3 large, 3 medium and 4 small trees removed from bank, chipped debris and ringed logs and left on site.
Job complete	3007540	95372	3 large, 3 medium and 4 small trees removed from bank, chipped debris and ringed logs and left on site.
Job complete	3007540	95372	Removed remainder of topped poplars x7. Dead trees x2. Cleaned and chipped brushwood. Removed trees as required
Job complete	3007540	95372	Removed remainder of topped poplars x7. Dead trees x2. Cleaned and chipped brushwood. Removed trees as required
Job complete	3007540	95372	Removed remainder of topped poplars x7. Dead trees x2. Cleaned and chipped brushwood. Removed trees as required
job complete		95607	Felled and Removed dead oak tree as required by council. Chipped debris and left site in tidy condition. Left log wood on-site. Task complete
Remove x8 trees <5mHI		95667	Cut down rhododendron trees 8 of them within camelia tree garden then removed and took to landfill
Job complete		95707	Felled wattles and measured to lengths as request from council. Chipped debris and left site in tidy condition. Left log wood onsite. Chipped mulch back into reserve around trees. Task complete.
Complete		95830	Felled and removed one of the two oaks a required. Chipped debris and left site in tidy condition.left log wood onsite cut up. Task partial complete. One more day left to fell last tree. Stumps to be ground and re seeded.

3459953	12/08/2024	25349	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Lakefront Reserve PK000026	2 x oak trees at lakefront near Wai-a-riki spa to remove. Stump to be ground.
3463303	14/08/2024	25377	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Jackson Park PK000007	Remove dying tree at entrance next to kindergarten. See attached
3470369	20/08/2024	25437	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Centennial Park PK000303	Centennial Park tree group near CT club - 3 trees on exposed brow, one of which fallen across fence into Holiday Park from Centennial Park. Clear fallen gum and remove exposed tall gum and leaning pine.
3474163	22/08/2024	25479	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Government Gardens PK000481	Redwood Government Gardens - Remove infected Redwood and dispose of carefully as a phytosanitary measure, as authorised by Stephen Rowlands
3484463	30/08/2024	25575	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Cochrane Street PK000602	3 Cochrane Street - Customer has requested: Cabbage tree is rotten dead needs to be taken out and is quite tall and could fall at any moment
3474469	22/08/2024	25486	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	Tree Removal - <5m Ht	3	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	2	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	3	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.

Complete		95830	Last remaining oak removed as required. Chipped debris and left site in tidy condition. Ground stumps to ground level. Top soil and re seeded. Removed log wood from site. One remaining log onsite to be cut up and carted away. Half a day left of work to be done.
complete		95909	Removed declining cypress tree as required. Felled stems, chipped debris and left site in tidy condition. Removed log wood from site. Task complete.
Job incomplete. closed f3016865	3017000	96068	Felled and removed fallen gum as required by council. Chipped debris and left site in tidy condition. Left log wood on-site and fallen log left stable. Job incomplete. Two tree to fell on another day.
Removed dying Redwoc	3017232	96144	Removed dying Redwood. Waste to tip including the stump. Job completed.
Job complete	3017312	96147	Removed dead cabbage tree as required by council. Chipped debris and left site in tidy condition. Stump to be grind and grass seed. Task complete
Job complete	3017317	96149	3 small, 2 medium red woods removed and brush remove and chipped, not all complete still need work
Job complete	3017317	96149	3 small, 2 medium red woods removed and brush remove and chipped, not all complete still need work
Job complete	3017317	96149	Felled 2 medium redwoods out of the remaining trees. Chipped debris and left site in tidy condition. Left log wood on site. Task incomplete. Estimate 2 more days work with equipment.
Job complete	3017317	96149	Field 3 large red woods, chipped rubbish, left logs on site. 1 more day required

3474469	22/08/2024	25486	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	3	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	2	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3474469	22/08/2024	25486	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	1	Matahi Spit Reserve PK000042	High lake levels have killed several redwood trees along the landward side of Matahi Lakefront Drive between the Lakeshore and the lagoon. Fell the redwoods to ground level and ring up the stemwood, chip the branch wood and remove from site. The stumps may be left, as may the various dead shrubs along the same area. These will act as a nursery crop for any natural regeneration or later native revegetation scheme.
3518745	26/09/2024	25906	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Martin Street PK000833	Please fell Douglas fir on riverbank to rear of 63 Martin Street, ring up stemwood and leave on site. All branch wood to be chipped and deposited on veggie patch as a composting pile. Deciduous tree to rear of fir - sever ivy stems from ground to 2m
3515168	23/09/2024	25863	7.1 - Tree Removal - < 250mm dia @dbh or 10 - 20m Ht	5	Matahi Road Rotoma	Exotic trees need felling and poisoning of stumps (ca. 5 wattles) on road berm sandwiched between Matahi Road and SH30 prior to weed-spraying and beating up with natives. Clear only up to the 60km/h sign on the SH30.

Job complete	3017317	96149	2 large red woods and 1 medium red wood and 3 small red woods removed, chipped all debris, and left all logs on site.
Job complete	3017317	96149	2 large red woods and 1 medium red wood and 3 small red woods removed, chipped all debris, and left all logs on site.
Job complete	3017317	96149	2 large red woods and 1 medium red wood and 3 small red woods removed, chipped all debris, and left all logs on site.
Job complete	3017317	96149	2 large red woods removed, chipped debris, cleaned site and left with no mess and left bigger logs on site.
Job complete	3017317	96149	2 large red woods removed, chipped debris, cleaned site and left with no mess and left bigger logs on site.
Job complete	3017002	96338	Climbed and rigged Douglas tree as required. Chipped debris and left site in tidy condition. Chipped mulch on site as requested. Left log wood onsite. Felled stem and left log whole to be cut up tomorrow. Task incomplete. Half a day left.
95372	3018962	96665	Removed wattle along roadside as required by council. Chipped debris and left site in tidy. Task complete. Left mulch onsite along spit.

3515168	23/09/2024	25863	Tree Removal - <5m Ht	2	Matahi Road Rotoma	Exotic trees need felling and poisoning of stumps (ca. 5 wattles) on road berm sandwiched between Matahi Road and SH30 prior to weed-spraying and beating up with natives. Clear only up to the 60km/h sign on the SH30.
3505153	13/09/2024	25763	Tree Removal - <5m Ht	1	High St PK000687	44 High St (trees are on Davidson St side) 2 Kowhai trees are dead that are on the berm and have been dead for a few years - @IC can this be actioned for removal please. Thanks Anne-Marie
3509632	18/09/2024	25802	7.2 - Tree Removal - 250mm - 500mm dia @dbh or 10 - 20m Ht	1	Waitawa Place Reserve PK000201	Removal of a cherry and apple overly encroaching fence and house in reserve behind 12 Te Ana Place
3509632	18/09/2024	25802	7.3 - Tree Removal - 500mm - 1000mm dia @dbh or 20m - 30m Ht	1	Waitawa Place Reserve PK000201	Removal of a cherry and apple overly encroaching fence and house in reserve behind 12 Te Ana Place
3522585	1/10/2024	25954	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Remove fallen Pohutukawa Sulphur point toilet block & Manuka
3522585	1/10/2024	25954	Tree Removal - <5m Ht	1	General Scheduled Rates - Activities	Remove fallen Pohutukawa Sulphur point toilet block & Manuka
3520657	27/09/2024	25937	Tree Removal - <5m Ht	1	Jackson Park PK000007	Remove Dead Tree, Springfield Road side, Picture attached
3520658	27/09/2024	25938	Tree Removal - <5m Ht	1	Jackson Street PK000725	Dead Kowhai Tree removal outside number 13 Jackson Street
3530067	8/10/2024	26020	Tree Removal - <5m Ht	3	General Scheduled Rates - Activities	Remove dead Manuka sculpture trail areas

Total trees felled: 991

95372	3018962	96665	Removed wattle along roadside as required by council. Chipped debris and left site in tidy. Task complete. Left mulch onsite along spit.
Job Complete	3019187	96782	Removed small dead kowhai as required. Stump to grind to ground level outside 44 Davidson street. Task complete.
Job complete	3036794	96928	
Job complete	3036794	96928	Felled and limbed prunus as required by council. Chipped debris and left site in tidy condition. Left log wood onsite. Task complete.
Removed large wind blo		97211	Removed fallen pohutukawa and infested manuka trees from behind toilet block. Also cleared away hebes and flax. Green waste to tip. Leveled site. Job completed but still need to do lawning.
Removed large wind blo		97211	Removed fallen pohutukawa and infested manuka trees from behind toilet block. Also cleared away hebes and flax. Green waste to tip. Leveled site. Job completed but still need to do lawning.
Job complete		97375	Removed dead tree as required. Chipped debris and left site in tidy condition. Stump to grind and re seeded. Task complete.
Job complete		97377	Removed dead tree as required. Chipped debris and left site in tidy condition. Stump to be grind and re seeded. Task complete.
Three large Manuka cut		97699	Removed dead Manuka trees from sculpture trail site.

Internal ID	Date	Document Number	Item	Quantity	RLC Asset / Street	Request Details
2340137	17/08/2022	16460	Plant 1.5l - 4l	608	Rotoiti Sewerage Plant	Year 3 Planting and maintenance
2340137	17/08/2022	16460	Plant 1.5l - 4l	608	Rotoiti Sewerage Plant	Year 3 Planting and maintenance
2340137	17/08/2022	16460	Plant 1.5l - 4l	277	Rotoiti Sewerage Plant	Year 3 Planting and maintenance
2340137	17/08/2022	16460	Plant 1.5l - 4l	200	Rotoiti Sewerage Plant	Year 3 Planting and maintenance
2340137	17/08/2022	16460	Plant 1.5l - 4l	300	Rotoiti Sewerage Plant	Year 3 Planting and maintenance
2078711	10/03/2022	14462	Plant 1.5l - 4l	36	General Scheduled Rates - Activities	
2214566	2/06/2022	15499	Plant 1.5l - 4l	30	General Scheduled Rates - Activities	Gap up gardens Hinemoa/ Fenton corner
2229690	13/06/2022	15627	Plant 1.5l - 4l	38	Government Gardens PK000481	
2245714	21/06/2022	15746	Plant 5l - 10l	1	Government Gardens PK000481	June 2022
2283446	15/07/2022	16033	Plant 11l - 39l	6	2.2 Juvenile trees (ea)	July 2022
2283446	15/07/2022		Plant 11l - 39l	4	2.2 Juvenile trees (ea)	July 2022
2283446	15/07/2022	16033	Plant 11l - 39l	1	2.2 Juvenile trees (ea)	July 2022
2286826	15/07/2022	16057	Plant 11l - 39l	9	Puketawhero Park PK000099	July 2022
2286826	15/07/2022	16057	Plant 11l - 39l	3	Capricorn Place PK000577	July 2022
2286826	15/07/2022	16057	Plant 11l - 39l	2	General Scheduled Rates - Activities	July 2022
2286826	15/07/2022	16057	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	July 2022
2286826	15/07/2022	16057	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	July 2022
2293535	20/07/2022	16106	Plant 1.5l - 4l	30	Hannahs Bay Reserve PK000485	
2297489	21/07/2022	16132	Plant 1.5l - 4l	243	Centennial Park PK000303	Peace Garden (Tree Trust) 500 plants & Peace Garden (Tree Trust) Coprosma Hedge
2297489	21/07/2022	16132	Plant 1.5l - 4l	192	Centennial Park PK000303	Peace Garden (Tree Trust) 500 plants & Peace Garden (Tree Trust) Coprosma Hedge
2297489	21/07/2022	16132	Plant 1.5l - 4l	139	Centennial Park PK000303	Peace Garden (Tree Trust) 500 plants & Peace Garden (Tree Trust) Coprosma Hedge
2297489	21/07/2022	16132	Plant 1.5l - 4l	6	Centennial Park PK000303	Peace Garden (Tree Trust) 500 plants & Peace Garden (Tree Trust) Coprosma Hedge
2297489	21/07/2022	16132	Plant 1.5l - 4l	127	General Scheduled Rates - Activities	Peace Garden (Tree Trust) 500 plants & Peace Garden (Tree Trust) Coprosma Hedge
2306473	27/07/2022	16204	Plant 1.5l - 4l	15	Waipa Road Sawmill MTB Carpark PK000236	Waipa Gardens - Gapping up hedges 20x Copromas repens 'Middlemore'
2362361	31/08/2022	16619	Plant 11l - 39l	2	General Scheduled Rates - Activities	Vaughan Rd 3x Magnolia
2312553	1/08/2022	16248	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	Ranolf St (Roundabout) 1x Betula jacquemontii
2326106	8/08/2022	16352	Plant 1.5l - 4l	15	Government Gardens PK000481	August 2022
2326106	8/08/2022	16352	Plant 1.5l - 4l	30	Government Gardens PK000481	August 2022
2326106	8/08/2022	16352	Plant 1.5l - 4l	62	Government Gardens PK000481	August 2022
2326106	8/08/2022	16352	Plant 1.5l - 4l	42	Government Gardens PK000481	August 2022
2337455	16/08/2022	16444	Plant 1.5l - 4l	27	Kuirau Park PK000025	August 2022
2316265	2/08/2022	16276	Plant 11l - 39l	1	Centennial Park PK000303	Centennial Park Block4, Section AA, Site 7 - 1x Totara
2316365	2/08/2022	16277	Plant 11l - 39l	1	Larcy Road PK000785	37 Larcy Rd - 1x Rhodo
2341535	18/08/2022	16470	Plant 11l - 39l	1	Marguerita St PK000830	92 Marguerita St - 1x Rhodo elegans

Work Description	REQ / RFS	Case Number	Field Service Actions Taken
		59577	Planting at rotoiti sewage treatment plant 608 in the ground + post holes bored.
		59577	Planting at rotoiti sewage treatment plant 608 plants.
		59577	Planting at rotoiti sewage treatment plant 277 in the ground
		59577	Planting at rotoiti sewage treatment plant, x200 natives, post hole borer x 300 + holes.
		59577	Planting at rotoiti sewage treatment plant, x 300 native plants.
		60031	Revamping bark gardens hinemoa street, removed old Coprosma prostrata and planted 36 rosemary plants, pb5 also 2 cu mtrs of topsoil from water shed as no supply in parks area
		61381	gapping up gardens Fenton, Hinemoa street. 15 sq mtrs
		64188	Prep cleared garden, added topsoil, rake out, plant 38 new plants, mulch garden, leaf blow tidy.
Emailed		64404	Replaced Magnolia, tied back to existing tree stakes site left tidy.
		65396	X6 kowhai tetraptera tapsell street, some training evolved in this time.
		65396	4x replacement kowhais at steeles lane.
		65396	Planting replacement trees at Capricorn, x 1 25L
		65396	9x totara 25L replacement hedge line x4 workers Puketawhero.
		65396	3x 25L Plagianthus regius x4 workers Capricorn pl
		65396	Plant x2 11l-39l trees
		65396	Plant x1 40l-100l tree
		65396	Plant x1 40l-100l tree
		65859	Planted 30x Grevillea
		65866	Planting at the peace garden, tree Trust assorted native plants x243
		65866	Planting peace garden at tree Trust, coprosma gradiflora 24 macropiper 35, aristotelia serrata 45, griselinia lucida 33, brachyglottis repanda 33.
		65866	Planting natives at the peace garden, tree Trust x 139 natives.
		65866	6x camelia transnokoensis planted.
		65866	Planting natives 127
		66226	15x middlemore waipa mill entrance gardens.
		66227	Plant x2 11l-39l trees
		66231	Plant x1 40l-100l tree
		66374	Plant total 15 plants added in fert tabs & quality mulch to match the surrounding gardens job finished.
		66374	Used 1 meter mulch from Landscape supplies PO - 13708. Garden planted fert tabs added, mulched planting areas only.
		66374	Planted carpark and covered with bark also grow tabs for each plant 62 no.
		66374	Planted 42 shrubs mixture some by rear deck along side of building, some along Hinemoa St side of building. Fert tabs used left tidy and 40 mtrs planted.
		66375	Removed old hebes from garden. Layed out and planted 27 x Hebe Quicksilver as replacements. Job completed.
		66475	Plant x1 11l-39l tree
		66476	Plant x1 11l-39l tree
		67033	Plant x1 11l-39l tree - rhododendron elegans number 92 margarita

2341635	18/08/2022	16471	Plant 11l - 39l	1	Centennial Park PK000303	CENTINIAL PARK - BLOCK 3, S12 (1x Acer rubrum) - refer to case 59655
2364896	31/08/2022	16639	Plant 1.5l - 4l	24	Rotorua Cemetery PK000963	Block up existing gardens - Locations to be blocked up; 2 x entrance gardens – plant with Arthropodium 'parnell'
2360387	30/08/2022	16604	Plant 1.5l - 4l	3	Rotorua Aquatic Centre PK000509	Gap up gardens
2399463	16/09/2022	16941	Plant 11l - 39l	5	General Scheduled Rates - Activities	Tree planting - Block 5 Section A Site 1, 3, 11 & 18 Tree planting - Block 5 Section C Site 32
2399964	16/09/2022	16947	Plant 11l - 39l	1	General Scheduled Rates - Activities	No.18 Pioneer Drive
2399764	16/09/2022	16945	Plant 11l - 39l	1	General Scheduled Rates - Activities	No. 157 Ranolf Street
2399563	16/09/2022	16942	Plant 11l - 39l	3	General Scheduled Rates - Activities	Tree Planting
2404185	19/09/2022	16980	Plant 1.5l - 4l	5	Rotorua Cemetery PK000963	Block up existing garden, plant standard rose & dianthus
2416788	23/09/2022	17081	Plant 11l - 39l	1	Centennial Park PK000303	Block 2 Section J Site 6 Tree Planting
2426589	29/09/2022	17157	Plant 11l - 39l	2	General Scheduled Rates - Activities	Tree planting
2426691	29/09/2022	17158	Plant 11l - 39l	2	General Scheduled Rates - Activities	Tree planting
2450033	12/10/2022	17324	Plant 5l - 10l	5	Whakaue Street PK001117	Plant 11l- 39l
2462131	20/10/2022	17413	Plant 5l - 10l	6	Urban gardens maintenance	173 of 209
2456001	17/10/2022	17370	Plant 1.5l - 4l	30	General Scheduled Rates - Activities	Centennial Park Block 4 - Gap up planting
2456001	17/10/2022	17370	Plant 5l - 10l	8	General Scheduled Rates - Activities	Centennial Park Block 4 - Gap up planting
2456001	17/10/2022	17370	Plant 5l - 10l	6	General Scheduled Rates - Activities	Centennial Park Block 4 - Gap up planting
2457470	19/10/2022	17380	Plant 1.5l - 4l	5	Government Gardens PK000481	Block up existing garden - Band Rotunda
2941866	4/08/2023	20859	Plant 1.5l - 4l	52	Government Gardens PK000481	August 2023
2941866	4/08/2023	20859	Plant 1.5l - 4l	8	Government Gardens PK000481	August 2023
2941866	4/08/2023	20859	Plant 1.5l - 4l	139	Government Gardens PK000481	August 2023
2941866	4/08/2023	20859	Plant 1.5l - 4l	7	Government Gardens PK000481	August 2023
2941866	4/08/2023	20859	Plant 1.5l - 4l	20	Government Gardens PK000481	August 2023
2941866	4/08/2023	20859	Plant 1.5l - 4l	63	Government Gardens PK000481	August 2023
2941866	4/08/2023	20859	Plant 1.5l - 4l	42	Government Gardens PK000481	August 2023
3118909	17/11/2023	22209	Plant 1.5l - 4l	8	Kuirau Park PK000025	Block up existing gardens
2780470	4/05/2023	19796	Plant Trees 40l - 100l or OG equivalent	1	Kuirau Park PK000025	Planting the Kings Coronation tree
2820452	25/05/2023	20039	Plant 1.5l - 4l	26	Government Gardens PK000481	Form new garden total renewal perennials archway bed & mulch
2841229	8/06/2023	20177	Plant 1.5l - 4l	50	Kuirau Park PK000025	Revegetation site preparation plant natives storm damage sites Lake Road end KP

67035 Plant x1 11l-39l tree Acer rubrum tree Trust Block 3 site f number 12 .

Emailed 67581 Prep existing gardens, gap up and spread 11 meters Cambium mulch.

Teams chat 67627 Plant 3 nandinas at aquatic garden. Job is done.

68128 Plant x5 11-39L - Block 5 Section A Site 1, 3, 11, 18 & Block 5 Section C Site 32

68132 Plant x1 11-39L Acer palmatum `Red Emperor`

68133 Plant x1 11-39L Acer palmatum `Bloodgood`

68134 Plant x3 11-39L Feijoa sellowiana

68525 Plant one standard rose 'In Loving Memory' in circle garden and gap up with 5 x dianthus. Grow tabs added, tied and staked rose.

68717 Plant x1 11-39L tree - Block 2 Section J Site 6

68953 Plant x2 11-39L trees - Prumnopitys ferruginea & Prumnopitys taxifolia

68954 Plant x2 11-39L trees - Metrosideros umbellata

69472 planted 5 x Acer Bloodgood in the Whakaue st tubs to replace some dead ones

69746 Redwood Park weed spraying

69824 Plant x30 1.5l-4l Erica spp., Plant x8 5l-10l Rhododendron spp.

69824 Plant x30 1.5l-4l Erica spp., Plant x8 5l-10l Rhododendron spp.

69824 Plant x6 5l-10l Rhododendron spp.

69920 Block up existing garden by band rotunda x5 perennials, apply fert.

77766 Section 8 gaps filled mixture perennials & few shrubs job completed.

77766 Blocked up playground bark garden, planted Asterias & Coprosma's 8 meters. No plants added where cars drive over end of garden.

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

77766

Planted rock lilies & 2 Astellias, moved 5 rocks into garden to stop pedestrians from cutting through, thermal has prevented more plants going in along edges. Silt removed garden mulched. this one washes out from the angles and the footpath.

Scented garden gap up ' 77767 Scented garden gap up with scented perennials and shrubs including:

1x Lavandula major

1x Gardenia jasminoides 'Fragrant Star'

1x Trachelospermum jasminoides,

1x Dianthus 'Pink Feather'

1x Dianthus resolution marbled pink.

2x Actaea 'Black Negligee'

1x TRAY (60) Dianthus 'Grace Double'

Job completed.

77948 Rewarewa planted in garden next to wisteria bridge. Planted for kings coronation.

78156 Purchase order 15742 for fine mulch. Garden striped & levelled, planted 26 perennials, & herbs also planted annuals at no cost to customer. Thick layer of mulch applied in keeping with existing area.

79064 Kuirau Park lake road end, reveg planting. Planted 47 x Leptospermum solarium and 3 x Sophora microphylla. No celery pine were available to plant. Job completed.

2844005	9/06/2023	20198	Plant 1.5l - 4l	12	Government Gardens PK000481	Full garden revamp Rave frontage & apply mulch
2838340	7/06/2023	20153	Plant 5l - 10l	1	Amohia Street PK000504	Replacing single plants
2870505	27/06/2023	20390	Plant 1.5l - 4l	9	Eruera Street PK000332	Gap up existing garden Eruera St
2972120	23/08/2023	21070	Plant 1.5l - 4l	177	Kuirau Park PK000025	Aquatic Centre Carpark - Remove and replant flaxes and plant new Grisellinia hedge
2933521	2/08/2023	20804	Plant 1.5l - 4l	33	Pukaki Street PK000401	Plant 1.5- 4 litre
2940765	4/08/2023	20849	Plant 1.5l - 4l	6	Whakaue Street PK001117	Plant 1.5 to 4l
2953325	11/08/2023	20943	Plant 1.5l - 4l	6	Ranolf Street PK000940	Garden Planting - Plant 1.5-4L
2951713	11/08/2023	20929	Plant 1.5l - 4l	31	Arawa Street PK000512	Gap up Plant 1.5l - 4l
3000733	8/09/2023	21274	Plant 1.5l - 4l	100	General Scheduled Rates - Activities	Revamp garden / Total renewal
3010203	14/09/2023	21352	Plant 1.5l - 4l	16	Government Gardens PK000481	September 2023
3016230	18/09/2023	21404	Plant 1.5l - 4l	77	Fenton Street PK000345	Block up / Sir Howard Morrison Centre two frontage gardens
3016330	18/09/2023	21405	Plant 1.5l - 4l	69	Hinemoa Street PK000695	Form new garden total renewal / Hinemaru St carving gardens
3027584	25/09/2023	21507	Plant Trees 40l - 100l or OG equivalent	8	General Scheduled Rates - Activities	September 2023
3027584	25/09/2023	21507	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	September 2023
3027584	25/09/2023	21507	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	September 2023
3027584	25/09/2023	21507	Plant Trees 40l - 100l or OG equivalent	2	General Scheduled Rates - Activities	September 2023
3027584	25/09/2023	21507	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	September 2023
3063223	16/10/2023	21797	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	October 2023
3063223	16/10/2023	21797	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	October 2023
3165695	18/12/2023	22609	Plant 1.5l - 4l	23	Government Gardens PK000481	Gap up perennial border
3319667	19/04/2024	24086	Plant 11l - 39l	3	General Scheduled Rates - Activities	Garden revamp/planting
3319870	19/04/2024	24088	Plant 11l - 39l	2	General Scheduled Rates - Activities	Garden revamp/planting
3400856	21/06/2024	24843	Plant 1.5l - 4l	480	General Scheduled Rates - Activities	Garden revamps on the Tutanekai Street bark gardens around Te Manawa
3400856	21/06/2024	24843	Plant 1.5l - 4l	480	General Scheduled Rates - Activities	Garden revamps on the Tutanekai Street bark gardens around Te Manawa
3391705	14/06/2024	24769	Plant 1.5l - 4l	25	General Scheduled Rates - Activities	Gap up Rave bark gardens by glass windows & buiding
3397160	18/06/2024	24813	Plant 1.5l - 4l	22	Government Gardens PK000481	June 2024

	79065	Full garden revamp front of Rave café. prep work, hedge removed to prevent homeless sleeping behind it. Planted 12 natives & mulched with high quality 1 metre mulch. 14 meters planted.
	79098	Replaced a missing Juniper in one of tge splitters at the Amohia/ Haupapa roundabout
	79789	
3004618	80416	Soil removed to make way for new bark. Planted 177 Griselinea Broadway mint planted with fert tabs. 5 m3 cambium mulch spread between plants.
Gapped up in various ga	81186	Plants gapped up in various gardens around Fenton /Pukaki intersection
Gap up garden	81348	Planted 6 Dianthus in small garden in middle of Whakaue st between Lime cafe and old Q E hospital
Plant x6 Carex testacea	81575	Planted 6 carex testacea
Gapped up gardens on t	81625	Gapped up gardens on the Arawa / Tutanekai corners after flax was removed
Planted in lake road by 5	82663	planted in lake road by St Micheals Church in middle of road, dianella x 100
Planted Carex testacea	83012	Planted Carex testacea behind panels Archway entrance Queens Drive t rooms side by bin. Replacing Buxus that weren't growing. 16 plants 4 mtrs gardens
Planted Carex 22 & Fest	83094	Planted Carex 22 & Festuca coxii 55 into gaps left from removing dead grasses poorly planted by contractor in Feb. Garden left tidy no mulch needed.
Full revamp both sides c	83095	Full revamp both sides of path under carvings. Festuca coxii 20 planted in front section of panels, carex t planted at rear of panels, mulched left tidy. big improvement.
Block 1 Section A Site 3	83350	Block 4 - Plant x8 40-100L trees: Acer palmatum 'Sango Kaku' (Senekaki)
Block 1 Section A Site 3	83350	Block 1 Section A Site 30 - Plant tree x1 - Acer palmatum 'Osakazuki' 45-100L
Block 1 Section A Site 3	83350	Block 4 Section AA Site 7 - Plant tree x1 - Podocarpus totara 'Matapouri Blue' 40-100L
Block 1 Section A Site 3	83350	Block 6 Section E Sites 9 & 11 - Plant tree x2 - Lagerstroemia indica 'De Puard' 45-100L
Block 1 Section A Site 3	83350	Block 8 Section A Site 45 - Plant tree x1 - Juglans regia 45-100L
Tree Planting 40-100L -	84183	Planted 1x 40Ltr Fuscospora cliffortioides in Block 5 walk way A site 20.
Tree Planting 40-100L -	84183	Plant x1 40Ltr Cornus 'Eddies white wonder' Block 2 Section I site 6a
Planted 23 perennials in	86853	Planted 23 perennials into gaps main perennial border
Garden total renewal x7:	91578	Revamp garden at heaphy place.
Garden total renewal x4:	91580	Revamp garden at Caulfield.
Total revamp of Tutanek	93317	CITY FOCUS: Putting compost in gardens as they were low. Good for the plants though. Planted up both sides by whitcoulls end towards Starbucks with new plants - 188 m2 TMP G28 STMS onsite.
Total revamp of Tutanek	93317	Removing shrubs and flaxes from Tutanekai Street Planting up new shrubs in gardens on south side of Hinemoa st
25 plants into gaps arou	93432	Prepared and planted 25 shrubs around Rave building also known as Arts Village. Site tidy.
Total garden renewal 14	93680	Removed Hebes, weeded, applied fertilizer and mulch, planted 22 lamandra.

3396553	18/06/2024	24806	Plant 1.5l - 4l	26	Kuirau Park PK000025	June 2024 GSR Kuirau Park
3428445	16/07/2024	25086	Plant 5l - 10l	50	Lakefront Reserve PK000026	GSR Lakefront July 2024
3428445	16/07/2024	25086	Plant Trees 40l - 100l or OG equivalent	1	General Scheduled Rates - Activities	GSR Lakefront July 2024
3423040	11/07/2024	25041	Plant Trees 40l - 100l or OG equivalent	3	General Scheduled Rates - Activities	Tree planting
3430856	18/07/2024	25108	Plant 1.5l - 4l	6	Government Gardens PK000481	GSR July 2024
3430856	18/07/2024	25108	Plant 1.5l - 4l	8	Government Gardens PK000481	GSR July 2024
3430856	18/07/2024	25108	Plant 1.5l - 4l	26	General Scheduled Rates - Activities	GSR July 2024
3442335	30/07/2024	25217	Plant 5l - 10l	130	General Scheduled Rates - Activities	Westbrook Reserve - Transplant Diets to carpark gardens
3442437	30/07/2024	25218	Plant 5l - 10l	62	General Scheduled Rates - Activities	Kotuku Street - Transplant Diets to Kotuku Street carpark gardens
3442537	30/07/2024	25219	Plant 11l - 39l	130	General Scheduled Rates - Activities	Centennial Park - Transplant Diets to Block 4 gardens
3472088	21/08/2024	25458	Plant 1.5l - 4l	100	Kuirau Park PK000025	August 2024 GSR
3504499	13/09/2024	25756	Plant 1.5l - 4l	39	General Scheduled Rates - Activities	Block up existing garden
3513235	20/09/2024	25844	Plant 11l - 39l	1	Mamaku Cemetery PK000818	Mamaku Cemetery - Tree planting
3513236	20/09/2024	25845	Plant 1.5l - 4l	1	Tarawera Landing Reserve PK000171	Tarawera Lookout - Tree planting
3539021	14/10/2024	26119	Plant Trees 40l - 100l or OG equivalent	1	Rotorua Aquatic Centre PK000509	Plant Rewarewa 45 ltr inside Aquatic Centre for mayor to finish off at 11.00

TOTAL TREES PLANTED 5754

Mulch spread under bus	93683	Kuirau Park foot bridge gardens. Planted new shrubs/plants to block up gaps. 26 x Plants used: 3 x Lavendula dentata pb5. 11x Dietes iridiode pb5. 12 x mixed Azaleas including Azalea Pax, Azales Aline, Azalea Kosmos, Azalea Helmut Vogel, Azalea Charlie. Fert tabs used too. Bark mulched with cambium bark. Job completed.
Planted 50 x Arthropodit	94489	Planted 50 7.5l arthropodium in and around the Lakefront playground.
Planted 50 x Arthropodit	94489	Tree bed and surrounding soil level raised above water level to prevent this tree drowning. 1 x Nyssa sylvatica 'Sheffield park' 80L planted, staked and mulched.
Dug three 2m x 2m tree	94637	Planted 3 large trees. 2 100l dawn redwood and 1 fagus purpurea 'Purple fountain' 3m3 topsoil used. Materials not working
Garden gap up tasks coi	94707	Gap up 5 x Coprosma Karo Red and 1 x Astelia chathamica 'silver spear' into existing bark garden.
Garden gap up tasks coi	94707	Remove some of existing soil as contaminated with oxalysis bulbs. Replace with new soil. Gap up existing garden with 8 new plants, water in.
Garden gap up tasks coi	94707	Gap up 13 x Phormium Jack Sprat and 13 x Phormium Surfer Bronze into existing Sudima bark garden.
Transplant Dietes iridioic	95231	Westbrook planting ixiodies x 133 including yesterday.
Transplant Dietes iridioic	95235	Transplant Dietes
Transplant Dietes to Blo	95236	Tree Trust Block 4 planting up ixodies x130.
Planted out, in reveg are	96048	Planted out, in reveg areas the following plants: 40 x Leptospermum scoparium 40 x Kunzea ericoides 10 x Dodonaea viscosa 'Purpurea' 10 x Pittosporum ericoides. Planted in the lake road end, horse trough area, and chicane area 150m2 area Job completed
Gapped up approx 25 sq	96964	Gapped up 25 sq mtrs of garden at Eruera/Hinemaru intersection with 15 mixed Dianthus and 24 Coprosma taiko left over from the Te Manawa revamp job
Plant x1 replacement 11	97122	Planting totara at mamaku cemetery.
Tarawera Lookout - Plar	97124	Tree planting at tarawera lookout, 1x Lance wood crass, 3x carex testacea
45Ltr Rewarewa planted	97959	Planted Rewarewa tree in Aquatic center lawn area. Dug out tree ring and mulched with compost. Staked tree. Job completed.